EXHIBIT 11

Trip Morano

From:

Tom Krause

Sent:

Wednesday, January 28, 2009 11:24 AM

To:

John Daniel

Cc:

Trip Morano

Subject:

FW: [WARNING: MESSAGE ENCRYPTED] Signal International - Eff: 1/30/09

Importance: High Attachments: Signal 2008 Primary Quote.pdf; Willis Property Submission.doc; 2009 SOV.xls; 2009 RMS

Workbook.xls; Inspection Report.pdf

JD

Can you rush clear this one for Trip? Layering noted below

From: Tom Cesare [mailto:Tom.Cesare@amwins.com]

Sent: Wednesday, January 28, 2009 10:56 AM

To: Tom Cesare

Subject: [WARNING: MESSAGE ENCRYPTED] Signal International - Eff: 1/30/09

Importance: High

We have a short fuse 1/30/09 account that we have some history on. The short story is:

For the 1/30/07 - 1/30/08 year Lexington wrote the \$10mm primary with AmWINS NY writing the \$15mm ex \$10mm with 3 wholesale markets.

 On 1/30/08 AmWINS NY guoted to competitive \$10mm primary with Westchester with the \$15mm ex \$10mm with the incumbent 3 markets.

Lexington in there desire to keep the business and increase their primary eventually got the renewal order on a \$25mm primary.

Anyway under the saying that it is better to be lucky then good (at least for the AmWINS markets who Lex beat), Hurricane Ike hit Lex for \$22mm!

Our retailer called me yesterday and advised that all along Lex was indicating that they where going to offer the \$25mm renewal @ \$1,400,000 which was up from \$1,150,000 expiring but yesterday they advised that they would only offer a \$10mm primary @ \$1,750,000!

We have Westchester who still likes this risk poised to offer a \$10mm primary @ \$1,400,000 though Sa 25 5 mil would have paid 10,478,484 is= they may have to cut back to a \$5mm primary @ \$1,000,000 (if the referral underwriter does not go along with the NY Managers \$10mm primary).

In any event we need for you to look at the following layering in order of preference:

- 1) \$10mm ex \$10mm @ \$350,000 layer ·
- \$5mm ex \$10mm @ \$225,000 layer 2)
- \$5mm ex \$15mm @ \$125,000 layer . 3)

\$5mm ex \$5mm @ \$400,000 layer

We are enclosing:

A) Westchester's \$10mm quote from last year this will be the same except:

1) The Named Storm/Storm Surge ded will be 5%/\$250,000 min (as opposed to \$1mm flat).

2) You can exclude Elood and Earthquake excess of \$10mm but Named Storm and ensuing Storm Surge will be included in the Wind Peril.

1/28/2009

Case 1:10-cv-01653-JPO -JLC Document 167-12 Filed 08/10/12 Page 3 of 65

B) Willis' 2009 Property Submission

C) The current 2009 SOV

D) An RMS Workbook that should be helpful to your modelers.

E) The most recent inspection report.

For clearance purposes:

Named Insured:

Signal International, LLC

Mailing Address:

PO Box 7007

Pascagoula MS 39568

Please review and advise quickly if you can authorize in these excess layers, time is short but this is one of those last minute deals that will bind.

Regards

Tom

Tom Cesare
Executive Vice President
Property Department Manager
AmWINS Brokerage of New York
Office 212-858-8925
Cell 917-859-6988
Email: Tom.Cesare@amwins.com

01/24/2008 15:09 FAX 2126218665

ACE Financial

@ 001/006



Quote # 01K3LG 001
Binder Policy #

TO: Tom Cesare

COMPANY: AmWins of New York

FAX: 704-943-9015

FROM: DATE SENT: BOUND DATE:

RE: Signal International, LLC

Thank you for submitting the captioned account. Please review this quotation carefully as the terms and conditions may be different than requested.

Effective Date:

01/30/2008 to 01/30/2009

Company:

Westchester Surplus Lines Insurance Company

Perils:

Risks of direct physical loss or damage including Earthquake and Flood, but including storm

surge

with other exclusions per policy forms and as specified below

Coverage:

Buildings, Business Personal Property including Stock, Business Income including Extra Expense, Dry Docks, Piers, Bulkheads, Wharfs, Cranes, Mics Equipment – and others as more

clearly defined in Willis Manuscript form

Limit of Liability:

Primary \$10,000,000 Per occurrence except as respects the following sublimits:

01/24/2008 15:08 FAX 2126218665

ACE Financial

Ø 002/008



Sub-Limits:

- 1. \$500,000 Accounts Receivable
- 2. \$5,000,000 Automatic Coverage on Newly Acquired Property, Property Damage and "Time Element" combined
- 3. \$500,000 Contamination Cleanup, land and water, in the aggregate during any Policy year
- 4. \$500,000 Contingent Time Element
- \$5,000,000 Contractors Equipment Leased, Botrowed, Rented or Loaned \$5,000,000 or 25% of the Property Damage and "Time Element Debris Removal and Cost of Cleamin
- 7. \$5,000,000 Demolition and Increased Cost of Construction Property Damage and Law, Ordinance or Regulation "Time Element" combined
- 8. \$10,000,000 Earthquake in the aggregate during any Policy year, Property Damage and Time Element combined
- 9. \$1,000,000 Electronic Media and Electronic Data, Property Damage and "Time Element" combined
- 10. \$250,000 Expediting Expense
- 11. \$10,000,000 Flood in the aggregate during any Policy year, Property Damage and Time Element combined. This aggregate does not apply to Flood resulting from a Named Storm.
- 12. \$100,000 Fine Arts
- 13. \$1,000,000 Interruption by Civil or Military Authority
- 14. \$1,000,000 Loss of Ingress or Egress
- \$1,500,000 Miscellaneous Unreported Locations Property Damage and Time Element combined per location
- 16. \$2,500,000 Omissions and Errors
- 17. \$2,500,000 Service Interruption, Property Damage and "Time Element" combined excluding all Transmission and Distribution lines greater than 1.000 feet from insured premises
- 18. \$5,000,000 Property in the Course of Construction, Property Damage and "Time Element" combined
- 19, \$5,000,000 Property in Transit
- 20. \$150,000 per occurrence / \$2,500 per day Equipment Rental Reimbursement Time Element:
 - 1. Extended Period of Indemnity 183 Consecutive Days
 - 2. Automatic Coverage on Newly Acquired Property 120 Consecutive Days
 - 3. Interruption by Civil or Military Authority 45 Consecutive Days
 - 4. Loss of Ingress or Egress 45 Consecutive Days
 - 5. Ordinary Payroll 90 Consecutive Days

All sublimits are per occurrence unless noted. None of these sublimits serve to increase the limit of liability, but instead are contained within it

Locations/Territory:

Territory is defined as the continental United States, Locations insured are as per schedule on file with the company

TIV: \$192,026,293

01/24/2008 15:09 FAX 2126218685

ACE Financial

Ø 004/00B



Policy Forms:

Willis Manuscript Form, including the following provisions:

- Definition of Named Windstorm to include wind driven water associated with a Named Windstorm (Storm Surge)
- 2. Definition of Flood to exclude wind driven water associated with a Numed Storm.
- 3. Flood Limit \$10,000,000 per occurrence and annual aggregate including 100 year Flood Plains
- 4. EDP Hardware included with no sublimit (EDP sublimit applies to Media and Data)
- 5. Contractors Equipment to include while on water at the insured's shipyards or while in transit between yards
- 6. Watercraft exclusion shall not apply to the dry-dock known as Dual Carrier while Dual Carrier is located within 5 miles of the insured's premises. This exclusion shall not apply to other dry-docks while located within 1 mile of the insured's premises.
- Valuation All Property Replacement cost basis except the dry-docks at ACV / Time Element Actual Loss Sustained.
- 8. Boiler & Machinery to be DIC/DOC over a Travelers B&M policy.
- 9. Paragraph #3 of the Transit Extension (page 55 56) needs to be deleted: This Policy does not insure export shipments after loading on board an overseas vessel, watercraft, or aircraft, or after ocean marine insurance attaches, whichever occurs first; or import shipments prior to discharge from an overseas vessel, watercraft, or aircraft, or until ocean marine insurance terminates, whichever occurs later. However, this exclusion shall not apply to:
 - a. Ferry shipments transporting over-the-road conveyances to, from, and between countries in Continental Europe, the United Kingdom, and Ireland:
 - b. Air and waterborne shipments within a single country; or air and inland waterway shipments to, from, and between countries in Continental Europe.
- 10. Section X: Global Insurance Clauses need to be deleted.
- 11. Any reference to Foreign Territories needs to be deleted.

Cancellation:

30 Days except 10 Days for non payment of premium.

Subject to:

Inspection and compliance with any recommendations deemed essential by the Company.

Mandatory
Exclusions and
Amendments:

All policy form exclusions including the following ACE Exclusions: Pollution & Contamination, Asbestos, Electronic Data/Cyber risk, Mold/Fungus, Nuclear Biological and Chemical Exclusions and Barthquake Sprinkler Leakage (unless otherwise specified in this quotation), Occurrence Limit of Liability Endorsement, Definition of Occurrence Endorsement.

Remarks:

Attached please find a Disclosure Notice required by The Federal Risk Insurance Act of 2002 ("The Act"). The premium charge for the terrorism coverage is set forth on the Disclosure Notice. This forms part of the overall premium quoted above for the Company's participation.

01/24/2008 15:10 FAX 2126218665

AGE Financial

國 005/006



Additional. Remarks:

Please be advised that we do not review Certificates of Insurance issued by you, or by any party, relating to this policy of insurance either for content or accuracy. Accordingly, we request that you do not provide copies of certificates to us for review or for our records. Authority is granted to you for the limited purpose of issuing unmodified ACORD Certificates (ACORD 25-S for Casualty and ACORD 24 for Property and Inland Marine) only. It is your responsibility to see that any Certificate provides an accurate representation of the coverage form and endorsements applicable to this policy at the time the Certificate is issued. Any modification of the approved ACORD forms specifically set forth above, or the issuance of a non-approved Certificate of Insurance ACORD or other is prohibited. Certificates of Insurance may only be issued as a matter of information. You have no authority by virtue of a Certificate or otherwise, to amend, extend or otherwise alter coverage afforded under this policy. Certificates of Insurance are never recognized as endorsements or policy change requests. You must submit a separate written request if an endorsement or policy change (including but not limited to adding additional insureds, loss payees and mortgagees and/or alteration of notice requirements for cancellation) is requested. In the event a policy change is requested, the underwriter will advise if the request is acceptable to the Company.

Quotation

Expiration Date: 01/30/2008

Done Soff.

01/24/2008 15:08 FAX 2126218665

ACE Financial

@003/00B



Coinsurance:

Property: Bus Income:

Nii% Nil% Valuation:

Property:

Replacement Cost

Bus Income: · Exceptions:

Actual Loss Sustained See Form Provisions for

exceptions

Premium:

\$1,000,000 + 100,000 Terrorisn

\$1,100,000

Includes Terrorism subject to exclusions, including but not

limited to Nuclear, Biological

and Chemical exclusions.

25% Minimum Earned

Premium

Any applicable taxes, surcharges or countersignature fees etc. are in addition to the above quoted figures. Please be advised that you are expected to comply with all state law requirements and your office is responsible for making State Surplus Lines Filings and remitting the applicable Surplus Lines taxes.

Deductibles:

\$100,000 Per Occurrence except:

a. Time Element Seven Times the Average Daily Value

- i. Time Element Deductible is in addition to any other deductible and is applied separately to all losses except those caused by Named Wind and Flood.
- b. Named Windstorm \$1,000,000 Per Occurrence as respects Named Storm including resulting Flood losses from storm surge - Combined Property Damage and Time element
- c. Flood: 5% per Occurrence of Total insured values at location(s) affected at time of loss subject to \$1,000,000 Minimum as respects Flood not resulting from a Named Storm - Combined Property Damage and Time Element
- d. Bulkheads \$200,000 per occurrence
- e. Dry Docks 5% of the scheduled value of the dry dock involved in the loss or damage, subject to a minimum of \$250,000 any one occurrence
- f. Leased/Rented Equipment \$100,000 or less \$5,000 per occurrence
- Leased/Rented Equipment greater than \$100,000 \$25,000 per occurrence



PROPERTY INSURANCE SUBMISSION

Effective From: January 30, 2009 To: January 30, 2010

Presented by: Willis of Alabama, Inc., Mobile

Signal International, LLC Table of Contents

General Information	1
Exeuctive Summary and Description of Operations	2
Underwriting Questions - General Information	
Named Insureds	4
Primary Property Coverage	

Signal International, LLC General Information

First Named Insured:

Signal International, LLC

Account Number:

698270

Mailing Address:

PO Box 7007 Pascagoula MS 39568

Financial Contact:

Chris Cunningham 228-762-0010

Inspection Contact:

Lisa Spears - same

Web Site Location:

www.signalinternational.com

Effective Date:

January 30, 2009

Expiration Date:

January 30, 2010

Producer:

John Bullock

Servicer: Marketer:

Joyce Johnson Zaleen Palmer

SIC Code/Industry:

Shipyard

Note: Willis will handle all Countersignature requirements with its affiliated offices.

Signal International, LLC Executive Summary and Description of Operations

Willis is pleased to present this submission on behalf of Signal International, LLC.

Signal International, LLC purchased the assets of FGO in 2003 and operates two yards in Pascagoula MS and four in the Port Arthur, Orange TX areas. The primary yards are the East Yard (MS) and the Orange Yard (TX). The principal focus is offshore drilling rig overhaul, repair, upgrade and conversion. Additionally, they provide services to the general marine and heavy fabrication markets. Additional information relative to current projects, safety, and operations is available on their website: signalint.com

Signal desires long-term relationships with insurance carriers who are both financially secure and can provide a competitive insurance program that respond promptly to their needs. Signal International, LLC is interested in insurers offering a flexible policy with broad coverage and requiring minimal servicing and endorsements. To this end, the Willis form wording is included in the submission. The specifications are to be considered as an outline for the designed program which is included in this submission. Proposals for broader coverage and expanded limits are encouraged.

Appraisals have been obtained and values have been updated; blanket coverage on a replacement cost basis (except as otherwise noted) is requested. The insured has updated the BI worksheet, and a Property Risk Assessment Report is being completed by Stephen Heller & Associates. While the final report is not ready at this time, a draft is included in the submission.

We thank you for your consideration.

Signal International, LLC Underwriting Questions – General Information

Explain all "yes" responses

- 1 Is the applicant a subsidiary of another entity or does the applicant have any subsidiaries?
- 2 Is a formal safety program in operation?
- 3 Any exposure to flammables, explosives, chemicals?
- 4 Any catastrophe exposure?
- 5 Any other insurance with this company or being submitted?
- **6** Any policy or coverage declined, cancelled or non-renewed during the prior three years?
- 7 Any past losses or claims relating to sexual abuse or molestation allegations, discrimination or negligent hiring?
- 8 During the last ten years, has any applicant been convicted of any degree of the crime of arson?
- 9 Any uncorrected fire code violations?

Explanations to "Yes" Responses

- 1) Per organization chart.
- 2) Yes see corporate overview
- 3) Usual to shipyard industry
- 4) Gulf Coast windstorm

<u>Yes</u>	NO
Yes 🖂	
\boxtimes	

Signal International, LLC Named Insureds

First Named Insured	Legal Entity	Interest	Description of Operations
Signal International, LLC	LLC	Owner of Signal International Texas GP, LLC (100%) and Signal International Texas, LP (99%)	MS assets and debt
Other Insureds	Legal Entity	Interest	Description of Operations
Signal International Texas GP, LLC	LLC	Owner of Signal International Texas, LP (1%)	
Signal International Texas LP	LP	·	TX assets and debt
Acon Offshore Partners, LP	LP	Owner of Signal International LLC (100%)	
ACON Offshore, LLC**	LLC		
Yates Offshore, LLC**	LLC		
Wilcar, LLC**	LLC		

*	l – Individual	NP - Not for Profit	LC - Limited Corporation	P - Partnership
	C - Corporation	S – Subchapter "S"	LLC – Limited Liability Corporation	JV – Joint Venture
	O - Other			

^{**}Added as respects policies except Workers Compensation

Signal International, LLC Property Coverage

TYPE: All Risks of Direct Physical Loss, Damage or Destruction of

Property Insured, including but not limited to "Boiler and Machinery," "Earthquake" and "Flood" and/or as more fully

defined in the Policy wording.

FORM: J(A) Insurance Policy and/or Companies Equivalent

INSURED: Signal International, LLC and any owned, controlled,

associated or affiliated subsidiary, company, corporation, organization, trust or association as now or may hereinafter be constituted or acquired; the interest of the First Named Insured in any partnership or joint venture, to the extent not otherwise insured; and any entity for which the First Named Insured has agreed to provide insurance, as their respective rights and

interests appear or as defined in the Policy wording.

MAILING ADDRESS: P.O. Box 7007, Pascagoula MS 39568

PERIOD: This policy attaches and insures for a period of 1 year, from

January 30, 2009 to January 30, 2010 beginning and ending at

12:01 AM at the above mailing address of the insured.

INTEREST: The insurable interest of the Insured in all real and personal

property of every kind and description, at a "location" or within 1000 feet thereof, including the "insurable interest of the Insured in property of others in the care, custody or control of the Insured" and at the option of the Insured, property of officers, directors and employees of the Insured while at a "location" or anywhere within the Policy territory when the officer, director or employee is acting on behalf of the Insured, but excluding personal effects; "Time Element"; and/or as may be more fully set out in the Schedule of Coverages attached

and as defined in the Policy wording.

SUM INSURED: USD25,000,000. Blanket Property Damage and "Time Element"

per "occurrence" all coverages combined.

ONLY TO PAY EXCESS PER OCCURRENCE OF THE

DEDUCTIBLE SET FORTH BELOW

DEDUCTIBLE: Program Deductible being USD100,000. in respect of all losses

other than the Schedule of Exceptions to Program Deductible

(for 100%) as attached.

Issue Date: January 28, 2009 SITUATION:

This Policy insures within and between the 50 states of the United States and Canada, and in the territories and possessions of the United States. However, as respects Contingent "Time Element" and Royalties this Policy insures worldwide except for loss or damage in any country where trade relations are unlawful as determined by the Government of the United States of America or its agencies, unless the Insured has been granted a U.S. Treasury Department of Foreign Assets Control license to do business in that country and then this Policy insures only to the extent legally permitted as a result of the issuance of such license.

CONDITIONS:

This insurance is subject to the same terms, clauses and conditions as the Policy Wording as included in the Underwriting Submission. Acknowledgement of agreement to this wording or any required amendments to it must be received by Zaleen Palmer at zaleen.palmer@willis.com no later than 01/15/2008.

Order will be subject to agreement of Insurer to issue formal policy documentation within 30 days of binding.

Schedule of Program Sub-limits (for 100%) as attached.

Schedule of Coverages as attached.

Watercraft Amendment – Exclusion E _ Watercraft is amended as follows: E. This policy does not insure watercraft. This exclusion shall not apply to the coverage on watercraft provided in "Off-shore Property" below (k). This exclusion shall not apply to the dry-dock known as Dual Carrier while the Dual Carrier is located within 5 miles of the insured's premises. This exclusion shall not apply to other dry-docks while located within 1 mile of the insured's premises.

Boiler & Machinery Coverage – Excess Coverage; Joint or Disputed Loss Agreement per Travelers Policy wording applies to this policy.

90 Days Notice of Cancellation

Electronic Date Recognition Clause

Mold, Mildew or Fungus excluded unless resulting from a "Listed Peril"

Electronic Media and Electronic Data excluded unless damaged by a "Listed Peril"

Asbestos Material excluded unless damaged by a "Listed Peril"

Pollution, Contamination excluded unless causing or resulting from a "Listed Peril"

Nuclear Reaction, Radiation or Radioactive Contamination excluded, but including Radioactive Assumption

War excluded

Terrorism excluded

Loss Payees, Mortgagees and Additional Insureds automatically included herein with advice to Insurer waived

Permission granted to Willis of Alabama, Inc. and/or the Willis Certificate Center to issue Certificates or Evidences of Insurance as and when applicable without advice

Replacement Cost including Capital Expenditure if actually repaired and replaced; otherwise Actual Cash Value; except dry-docks and Scheduled Contractors Equipment at Actual Cash Value. As respects Leased/Rented Equipment, Replacement Cost valuation applies if required by lease agreement.

Valuable Papers and Records and Electronic Media and Electronic Data at Cost to Reproduce, Re-create and Research

Selling price on "finished stock"

Actual Loss Sustained as applicable

No Coinsurance

Omissions and Errors

Unlimited Vacancy

Waiver of Subrogation (prior to loss)

Priority of Payments/Drop Down Provisions (applicable only to excess participations)

CHOICE OF LAW & JURSIDICTION:

Choice of Law: Mississippi

Jurisdiction: USA

Service of Suit: LMA 5020 or LMA 5028 (where applicable

Issue Date: January 28, 2009

PAYMENT TERMS:

US Premium: 45 days from policy inception

BROKERAGE:

10%

TAXES PAYABLE BY INSURED:

Insurance premium taxes, guarantee fund surcharges, government schemes and any other fees due in jurisdiction in which the Insured operates and customarily payable by the

aurod

Insured.

INFORMATION:

As per the Willis Underwriting Submission dated 01/15/2009, including Loss History contained therein. For premium purposes only, the 100% PD/BI values are USD211,328,279.

SCHEDULE OF PROGRAM SUB-LIMITS OF LIABILITY (FOR 100%) AND TIME LIMITS

Application of Program Sub-limits of Liability

- The Program Sub-limits of Liability apply per "occurrence" in excess of any applicable deductible, unless otherwise stated
- 2. The Program Sub-limits of Liability represent the maximum amount recoverable in respect of the limited coverage over all Underlying, Contributing or Excess Insurance combined.
- 3. The Program Sub-limits of Liability shall not increase the Limit of Liability (Sum Insured) of the Policy.

	Entite of Clabinty (Sum insured) of the Folloy.
USD500,000.	Accounts Receivable
USD2,500,000.	Automatic Coverage on Newly Acquired Property, Property Damage and "Time Element" combined
USD250,000.	Contamination Cleanup, land and water, in the aggregate during any Policy year
USD500,000.	Contingent "Time Element"
USD5,000,000.	Contractors Equipment Leased, Borrowed, Rented or Loaned
USD150,000.	Contractors Equipment – Rental Reimbursement, but not more than \$2,500 per day for up to 60 days
USD5,000,000. or 25% of the Property Damage and "Time Element" claim payable under this Policy, whichever is greater.	Debris Removal and Cost of Cleanup
USD250,000.	Decontamination Costs
USD5,000,000.	Demolition and Increased Cost of Construction Property Damage and Law, Ordinance or Regulation "Time Element" combined
USD25,000,000.	"Earthquake" in the aggregate during any Policy year, Property Damage and "Time Element" combined.
USD1,000,000.	Electronic Media and Electronic Data, Property Damage and "Time Element" combined
USD1,000,000	Expediting Expense

Issue Date: January 28, 2009 USD25,000,000.	"Flood" in the aggregate during any Policy year, Property Damage and "Time Element" combined. This aggregate does not apply to Flood resulting from a Named Storm.
USD500,000.	"Fine Arts"
USD1,000,000.	Interruption by Civil or Military Authority
USD1,000,000.	Loss of Ingress or Egress
USD1,500,000.	"Miscellaneous Unreported Locations," Property Damage and "Time Element" combined per "location"
USD2,500,000.	Omissions and Errors
USD2,500,000.	Service Interruption, Property Damage and "Time Element" combined
USD10,000,000.	Property in the Course of Construction, Property Damage and "Time Element" combined
USD10,000,000.	Property in Transit
USD500,000.	Valuable Papers and Records
SUD1,000,000	Exhibition, Fairs and Trade Shows
USD1,000,000.	Leasehold Interest
USD1,000,000.	Fire Department Service Charges
USD1,000,000	Personal Property of Officers and Employees
USD100,000.	Claim Preparation
USD1,000,000.	Research and Development
USD2,500,000.	Business Income Interdependency Coverage
USD2,500,000.	Increased Tax Liability
USD1,500,000.	Business Personal Property at Offsite Storage Facility
USD500,000.	Plans, Blueprints, Drawings, Models or Specifications
USD5,000,000.	Newly Acquired Equipment (120 days to report)
USD5,000,000.	Waterborne Equipment

Issue Date: January 28, 2009

USD3,000,000. Unscheduled Equipment, with no individual item to exceed

USD250,000.

USD1,000,000. Miscellaneous Tools, with no individual item to exceed

USD100,000.

In the event of a claim, payment shall not exceed the "Time Element" loss incurred during the following Time Limits

Time Limit The following shall apply

120 Consecutive days limit Extended Period of Recovery

120 Consecutive days limit Automatic Coverage on Newly Acquired Property (this Time

Limit begins on the date of knowledge of such Location by the

Insured's Finance Department)

30 Consecutive days limit Interruption by Civil or Military Authority

30 Consecutive days limit Loss of Ingress or Egress

90 Consecutive days limit Ordinary Payroll

SCHEDULE OF EXCEPTIONS TO PROGRAM DEDUCTIBLE (FOR 100%)

As respects Time Element

10 days (in addition to property damage deductible, except for

specific perils referenced below)

As respects Bulkheads (and any attached equipment)

USD200,000, any one occurrence

As respects to dry docks (and any attached equipment)

2% of the actual cash value of the dry dock involved in the loss or damage, subject to a minimum of USD250,000. any one

occurrence

As respects Cranes, Booms, Derricks and Lifts

USD25,000, any one occurrence

As respects Blanket Leased/Rented Equipment (other than cranes) with values less than USD100,000

USD5,000. any one occurrence

As respects Blanket Leased/Rented Equipment (other than cranes) with values greater than USD100,000

USD25,000, any one occurrence

As respects Named Storm including Flood resulting from Named Storm

5% of values affected at time of loss including building, contents, equipment (not including dry-docks or "Time Element") involved in loss or damage arising out of a "Named Storm" including resulting "Flood" loss from Storm Surge regardless of the number of coverages, locations or perils involved, and subject to a minimum of USD250,000, any one occurrence.

As respects Flood (except Flood resulting from Named Storm)

5% of values affected at time of loss including building, contents, equipment (not including dry-docks or "Time Element") involved in loss or damage arising out of a "Flood" (not resulting from a "Named Storm") subject to a minimum of USD1,000,000. any one occurrence.

If two or more deductible amounts in this Policy apply to an occurrence the deductibles shall be applied separately but the cumulative deductions so calculated shall not exceed the largest deductible applicable

SCHEDULE OF COVERAGES IN POLICY

Property Damage

Accounts Receivable

Automatic Coverage on Newly Acquired Property

Brands and Labels/Control of Damaged Property

Claim Preparation Expenses

Consequential Loss

Contamination Cleanup

Debris Removal and Cost of Clean Up

Decontamination Costs

Defense Expenses

Destruction of Property at the Order of Public Authority

Electronic Data Processing Equipment, Media and Data

Expediting Expense

Fine Arts and Antiques

Improvements and Betterments

Increased Tax Liability

Land Improvements

Operation of Building Laws

Personal Property of Officers, Directors and Employees

Preservation of Property

Property in Course of Construction

Property in Transit

Protection Devices

Removal

Service Charges

Service Interruption (no distance limitation, no waiting period to apply)

Valuable Papers and Records

Case 1:10-cv-01653-JPO -JLC Document 167-12 Filed 08/10/12 Page 24 of 65

Issue Date: January 28, 2009

Time Element

Business Interruption Gross Earnings

Expenses to Reduce Loss

Extra Expense

Leasehold Interest

Rental Value

Contingent "Time Element" (direct suppliers and receivers, attraction properties)

Interdependent Time Element

Interruption by Civil or Military Authority (five mile limitation)

Law, Ordinance or Regulation

Loss of Ingress or Egress (five mile limitation)

Rental Value

Royalties

Service Interruption (no distance limitation)

Soft Costs (Property in Course of Construction)

Signal International, LLC Statement of Values - Blanket by Location as of 01/14/09

Proprietary Information

THE HALL	Т	_		_	1	_	1		ı-	}	Τ	Υ	Т	Т	٦	٦				Γ	Т	Т	7	٦	٦	7	
waten Mon	_	_	_	Ϋ́es	L	-	L	L			-	-		1	-	-				L	1	4	-	-	-	\dashv	
Alams		χes	Kes	ટ	_	_	_	-	Ϋ́	Ϋ́es	8	ž	-	+	-	_					+	-		_	-		
Sprktra			L	2 Yes	_	_	L	_	L	_	ļ	L	1	1		\Box		_	_	_	-	-	_			Ц	
Stories	-	_	L	1	-	-	-	\vdash	-	-	+	╀	+	+		_	-	l	_	ŀ	+	+			Н	Н	
Conef				Ş			ļ									ľ											
Yest Bult		\vdash	\vdash	7		t	\dagger	+	t	t	t	t	+	1	-	-		T	\vdash	t	+	1			-	П	
1964.Duni		L	L	L	\perp	\downarrow	+	+	1	+	+	+	+	-	_	_	-	H	-	-	1	-	_		-	Н	
8				10.203	200																-						ĺ
		L	ļ	-	-	1	1	-	1	+	+	+	+	_	-	-	-	┞	┝	+	4		_	L	-	-	
								ĺ						g													
Catanente				- Parity	100				-	,		,	g	hop Ya		3											
6		Xad	Y X	,		3			16,75	1 ×			1 900g	tckley S	8	dmino											
		12	207 Avy Wast Yard	Contract of the Contract of th	3 5	2,338,10/ mai camp samp	2	+	, vo	3 8	1,857,121 USON 1021,108,1	1,554,800 Sount 1980	5 86	1,979,300 Buckley Shop Yard	16.795 Office	748 845 Admin office	2	-	22	2	8	450	8	g	8	133	1
Wite Control		AD SAN 184 East Yard	,		\$.	7,700	12,12,43		A occ con Dock Yard	200	8	ğ	38,576,498 Urange 1 aro	1,979,	19	748	50 564 584	5	CC8 CXX CX	17	47,202,000	28,683,450	5.000.000	2 000 000	10,000,000	211,328,275	
j B						1														1						1	
					٠,	٠,	2		<u> </u> .		2	ام	.,	s	5		٠, ١	•	٠	^	•	.,		. -		, 0,	
Tine Element ALS									١												47,202,000					47.202.000	
				.														l			74					47.	•
20 20 11																	Ì			4	u					١,,	٠
		Ť	1	7						1												28 583 450	000	000'000'0	2000000	10,000,000	
25 Page 25 Pag					1					Į												28.6		5 3	3 5	2,5	į
ű									1											2				,	١,	با م	•
British Erydocia		1	3	g	-	1	8	+	1	8	9,00	8	140	T	,†	:		3	1	164	ľ	Ť	1			22 977 464	
Š 5			13,350,000	1,575,000			14,925,000			13,600,000	1,410,620	1,087,500	2,851,044				1	18,949,164	1	33,874,164						22 87	į
0 4 2 2			1			İ			l																		
68		+	۰۰ تد	2	8	-	 	-	-	545,100 \$	8		24	٠ ا	37,4	16,795	ξ.	8	4	\$6 \$6				Ì		1	9
der Pros Constituti			14,539,584	883,700	494,500	557,277	16,475,061			645.1	268.700		13 769 754 \$		į.	16,	748,845	15,993,894 \$	İ	32,468,955						00 000 00	4
Į.		١	=				#						-							(ra		ļ				ľ	
5 n																	١										
e co		-	8	8	8	8	30			\$	8	\$77,300 \$	8	3 5	3	<u>~</u>	~	\$ 082		\$ 012		Ì					2 20 140
Real Prop Building/Structures	\$		21,653,600	1,938,300	946,700	1,780,830	26,319,430			724,880	187,800	477.3	24 DEE 200	2	1,434,500			24,780,280 \$		51,099,710							2
16			~				7						1	1				,				1					
ů			u	u		'n	,,		_	u,	5,	5		4	s	s	S	s		S				0,000			•
Gis	tė		¥	SM.	SH	SY.	L	_		≥	×	ř	1	<u> </u>	≱	<u>κ</u>	7	-	-	L	$\frac{1}{2}$			Tan \$25			_
		1	skix	뫍	왕	onla				tur	lat.	Page				c								Blanket Leased/Rented Equipment no one item greater than \$250,000	gia Gia	$ \ $	
	1		Pascagoula	Pascagoula	Pascagoula	Pascagoula				Port Art	Part Arthur	Sahine Pass		Cange	Orange	Houston	Orange							s item g	y one it		
			Ť	-	٦	Ť	T			ľ	Ī	ľ	1					Γ			1			t no ont	Blanket equipment less than \$100,000 any one item	Blanket Owner Furnished Equipment (OPE	ĺ
		i	Pky	P	≽	P																Ę,		uipmen	10 S100	Equipme	
	8806		assotte	tagility.	Fe. F	assotte				S Byd	way Or	Ava	1	ğ	ē,	3, 6	l B					dempt	ent	inted Ec	less th	Daysin	
		z	1601 Bayou Cassotte Pky	2 3500 Port Authority Rd	3 3401 Jamy St. Pe' Hwy	4 601 Bayou Cassotte Pky	SW		_	5 2500 M.L.King Blvd	6 2350 S. Gulfway Dr	7 6830 S First Ava		8 91 WEST Front SI	g 65 Green Ave.	10 1011 Highway 6	11 905 Pier Road	ř				Blanket Business Interruption	Scheduled Equipment	sedRe	пошен	nar Fur	
		IS DIVISION	16018	3500	3401	\$ 601 B	Total MS	_	NOISION	5 2500	\$ 2350	7.6830	3	2 2 2	9 65 G	100	198	Total T	-		250	rket Bus	paluba	sel les	keted	oket Q	1
Lo	o Ø	AS L		Γ	}	1		1			1	1	1					L		Ş	2	쭚	SS	lä	18	a	١

Page 1 of 1

Signal International, LLC Statement of Values 1/16/2009

Proprietary Information

ropiletaly information	-					1/16/2009				000000000000000000000000000000000000000		30000	1000
												*****	······································
Bldg Loc	(Sta	Building/Structures Replacement			Sulkhead, Brydocks, Scheduled Equement	j	SHOOMING		rear Bu	Sprktr Storie	Alerm	Cas
NOISION		-		16.5.111		***							se
1 Total 601 Bayou Cassotte Pky	Pascagoula	SP.	21,653,600	S	14,539,584 \$	13,350,000 \$	49,543,184	East Yard					1:
					-	3,150,000		Bulkhead		1998		_	1(
					43	10,200,000		Dry-dock: Dual Carrier			-	4)-(
		6-2	İ					Work Platten		1998	-	_	CV
		69						Gantry Crane Rail		1998		\neg	'-C
· E001		₩	ന്		2,521,408			Administration Building	36,484	1998 Masonry		+)1 ĕ :
E002		\$		\$ (230,000			Compressor Bldg.	1,407	1985 Metal		운 :	65 92
E003 .		\$		\$ (395,000			Electrical Shop	9,378	1995 Metal	2	2	53
E004		\$	6	\$ (4,300,000			Fab (Pipe Shop	85,175	1985 Metal	2	2	<u>-</u> ا بۆ
E005		4		\$ (592,800			Machine Shop	13,511	1995 Metal	_	원:	P ğ ;
5005		ьэ		\$ (195,600			Maintenance Shop	4,633	1995 Metal	2 :	ટ :	O
E007		s		\$ (•			North Restroom	1,540	1995 Metal	2	2 :	ĕ į:
8003		69	48,400	\$	30,100			Security/First Aid	918	1995 Frame	2	2	J ĕ :
E009		54		\$ 0	•			South Restroom	1,575	1995 Metal	운 -	2	Ž Į
E010		6.5	521,700	\$ 0	2,500,000			Warehouse 1/Tool Room	18,304	1995 Metal	2	1	<u>ر</u>
E011		65		Included above	above			Warehouse 2/Tool Room	19,389	1995 Metai	2	2	ĕ
E012		£			above			Warehouse 3/Tool Room	19,601	1995 Metal	모	윈) () ()
E013		83			1,063,876			Blast/Paint	11,361	2008 Metal	2 ~	ટ્ટ	ÇI
E014		6.5		\$ 0	85,300		,	Rigging Bldg	2,020	1990 Metal	£	ş	Je Ve
E015		5		-				Fuel Station	487	2005 Masonry	-	2	֚֚֓֞֟֝֟֟֟֟
F016		153		5.	136,000			Primary Time Clock	320	2005 Fiberglass		ટ	ğ J
15017		S		<u></u>	102,000			Secondary Time Clock	311	2008 Metal	2	윤	<u>t</u>
E018		\$			24,800			Paint Storage (Blast Yard)	1,165	1998 Metal	2	ટ્ર	1,6
F019		6.5		\$ 0	52,800			Trailer(s), 3 QA/QC	1,899	2005 Metal	2	ટ્ર	. <mark>7</mark> ĕ
5000		S	10,900	S	33,500			Trailer, Engineering	1,204	2006 Metal	2	2	- ğ
. 6021		3			97,400			Trailer (s), 6 Superintendent	3,504	2005 Metal	2	2	2 8
. 15000		59	22,800		15,900			Trailer, Safety	572	2005 Metal	₽	2	<u>×</u>
E003		63	27,000	s o	52,300			Trailer, Document Control	1,880	2008 Metal	운	ટ્ટ	ĕ
PU37		63			2,000,000			Quonset, Scaffold	1,144	1950 Metal	2	웆	Xe Ve
5005	-	63			30,800			Portable Storage (9)	1,168	2005 Metal	운 -	운) (
F036		49		4	80,000			Production Office, Rental				-	C
2 Total 3500 Port Authority Rd	Pascagoula	WS &	1,938,300		\$ 002,888	1,575,000 \$	4,387,000				$\frac{1}{1}$	-	8
		_			s	1,575,000		Bulkhead				7	/1
WOO!		5	1,324,000 \$	\$	313,800			Fab/Pipe Shop	12,276	1888 Metal	2	2	<u>Q</u> /
W002		5		\$ 0	65,300			Mechanic Shop	1,547	1998 Metal	-		/1 /8
EUUM)		\$	\$ 61,000 \$	\$	•			Restroom	827	1998 Masonry		1	2
NO CONTRACTOR OF THE PROPERTY		649		\$ 0	250,000			Receiving/Warehouse	6,150	1990 Metal	2 30	ટ	š
WOOK		6.0		0				Fuel Station	589	2008 Metal	2	7) W
Social		S	-	\$ 0	52,900			Trailer, Production	1,904	2006 Metal	2		<u>}(</u>
W000					115,000			Compressor Bidg.	404	2005 Metal	8	2	Ç X
/nnax		3		\$ 0	27.800			Trailer, Safety	1,000	1990 Metal	-		Xe.
SOUNT STORY		8		0				Production Office	164	1995 Masonry	1 No	No	Ke <mark>©</mark>
WOUS		1											of
						7							6
0105/257						5 - a5pt							5

Signal International, LLC Statement of Values 1/16/2009

		Aler Spriv Stor	drd fes	Metal 1 No No	No Yes	No No	No No	2 Yes Yes		Yes	1 Yes Yes	1 Yes Yes	1 No Yes		\top	No Yes	2007 Melai 1 No No Yes	C		Do	ON ON ON ON ON ON ON ON ON ON ON ON ON O	Metal 1 No No	1 No Yes		1 No No	1 No Yes	Wood 1 No No		2		1 No Yes	- -	ON NO	\top	8/	Cey No No 1	c _N	Service Market Control of the Market Control	2		A No	ON TO	2	2	1 No No Ye	of	6
		- 500 L		206	_	_		19,203				X	864 Each		28	_	_				. 636	167	_			1,421	252	171			4,602	2,708	0,447	451		133	13.430	20.436	017,01		200 20	52,525	_		35,240		
			Comments	Time Clock Alley	Paint Storage (Blast Yard)	Electrical Storage	Security Building	0 Training Building		19 Bunkhouses	Kitchen	Laundry Room	2 Lounges	Scaffolding	Shower Room	Mancamp Office/Storage		7			Limo Clark Allow	Guard House	Maintenance/Repair Shop	Warehouse-1	Warehouse-2	Cafeleria	Security Hut	Time Keeping	ig North Yard	Bulkhead	Shipping/Receiving	Maintenance/Repair Shop	Warehouse-1			Guard House Time Clocks	Waraharea 3	Walanouse :	Waterouse-2		Bulkhead	Blast Pit #1	Computer Terminal	Guard House	Light Fab Shop		
values	6		Total Values					\$ 1,441,200	\$ 2,338,107									\$ 57,719,491		\$ 14,969,980									\$ 1,867,120						\$ 1,564,800					38,370,498						,	
statement of values	1/16/2009	Bulkbead Drydocks. Scheduled Equipment	Š					~ *										14,925,000		13,600,000									1,410,520						1,087,500	1,087,500				2,851,044	\$ 2,851,044						
ñ		a	ontents RCV	34,000	15,700	9,200		494,500	557,277	213,400	218,256	65,000	33,000		11,621	11,800	4,200	16,475,061 \$		645,100 \$	69	51,000	One'e	109,000	406,300	15 300	7 000	18,000	268,700 \$		97,800	,	136,900	34,000	\$	8		•		13,769,754 \$		100,000	20,000	6,100	1,524,200		
		Buiding/Structures: Replazement	Cash Value*	\$ 00	11,000 \$	\$ 005'6	25,000	946,700 \$	1,780,830 \$		237,425 \$	91,955 \$	\$ 02,200	209,940	121,500 \$	35,000 \$	3,310 \$	26,319,430 \$		724,880 \$				135,000 \$	482,700 \$	5 005,72 58,500		2 280 2	187.800 \$		49,300 \$	S	128,500 \$	10,000 \$	477,300 \$		1,400 \$	268,000 \$	207,500 \$	21,955,700 \$		556,800 \$	32,400 \$		1.517.400 \$		
			Late	63	64	s	43	MS \$	1	1	63	63	ψĐ	69	S	49	S	w		₹ \$		sp (44	s (<i>A</i>	A	9 6	9 6/3	, s	1	63		6-9	\$	χ.		69	\$	\$	TX \$		s	s	6.9	65	•	
			£					Pascagoula	Γ											Port Arthur									Port Arthur						Sabine Pass					Orange							
	Froprietary information		Street					3401 Jerry St. Pe' Hwy	601 Bayou Cassotte Pky									TOTAL MS		2500 M.L.King Blvd									2350 S. Gulfway Dr						6830 S. First Ave					91 West Front St							
	Fropries		dg# oc#	W010	W011	W012	W013	3 T001	4 M001										TX DIVISION	5 Total		D001	D002	E00G	D004	5000	800) non	1100	0 10	אטטא	NDO2	N003	N004	7 Total		2001	2005	S003	8 Total		ORDO	OBOUS	COROC	2000	5020	

12 Page 28 of 65

Signal International, LLC Statement of Values

1/16/2009

Proprietary Information

200000000000000000000000000000000000000		100000000000000000000000000000000000000	10.000	100000	2010 202020000000000									***
ENd LC			ŞI	B. Iden	BuidhgiStrictures Replacement		Bulkhead Brydocks. Scheduled Equipment				Con Year Bu	Sprkti Storie	Alam	
g# c#	Strad	ð	ale	Cas	h Vake'	Contents	AQX	Total Values	SUPPLIES STATES		SI .	- 1	M-1	1
OR005				(4)	13,000,000 \$	5,512,900			Main Fab Shop-N,C,S Bay	215,686	1942 Metal	운 : - ·	2	
OR006				\$	\$37,000 \$	725,000			Maintenance Bldg	17,187	1942 Metal	2	2	
OR007				\$	\$ 000'02	008'09			Joiner Warehouse	1,440	1960 Metal	<u>2</u>	ટ્ટ	-1
OR008				65	29,500 \$				Paint Storage	2,752	1942 Metal	2	2	\subseteq
OR00				6-5	104,800				Pipe Shop	7,049	1942 Metal	<u>₽</u>	ટ્ટ	4
02010				65	622,200 \$	-			Warehouse-2 (Consumables)	21,590	1975 Metal	2	Ş	-1
OR011				643	955.000 \$				Power Plant Building (10)	200	Metal	2	2	=
OROTZ				63	1.379,000 \$	1,747,100			Preassembly	68,352	1942 Metal	2	S	\sim
OROTI				63	8.300 \$	•			Assembly Area (muster area)	244	1997 Metal	<u>8</u>	2	4
OB014				63	410,500 \$	437,000			Warehouse-1	20,567	1942 Metal	운 ~	2	_
OR015				69	4 600 \$				Security Trailer	316	1995 Metal	운 -	_	
9000				. 64	397.800 \$	47			Warehouse 4	19,928	2006 Metal	₽		\sim
7,000				v	16.400 \$	46,600			Welding Storage/Tool Room	1,104	1985 Metal	2	2	-
9000					27.900 \$				Maintenance Bldg (drive through)	575	1960 Metal	2 	ટ	-
01000					307 800				Pipe Warehouse	16,264	1942 Metal	. NG	ş	-
31020			$oldsymbol{\perp}$	3 6	3 900				Time Clock Alley Primary	244	2008 Wood	1 No	Ş	
O'SO'S					319 100 \$				Warehouse 3	15,990	1975 Metai	~ S	운	
OK021				9 0	567 600 \$				Warehouse 5	23,171	2006 Metal	- S	Ş	
04027	7			> 6	9 000 3CY				24.1	22,113	1975 Metal	2	S	-
OROZ	3		1	9 6	400,200	159 000			Outhting	6,582	1975 Metal	- N	SN.	
OR024	4			A	9 000	000 75			Time Clock Alley Secondary	2	2008 Metal	-S	2	
OR025	5			A .	90	736 067			Production Office, Rental			-	_	-
OR026			ļ	و وس				1 979 300						
9 Total	65 Green Ave.	Orange	×	,	4 000 000 v				Office Building	1,365	1993 Masonary	운 ~	Ϋ́	Η.
80001			-	A (4 006,900				Shop	12,144	1983 Metal	% ₩	Yes	-
BU002	2			A	* 002/0201							$ \cdot $		-
	4044 Linkway 8	TO TO TO	7	6	S	16.795		\$ 16,79	16,795 Office			-		-+
2 4	905 Pier Rd	Orange	<u> </u>	(A)		748,845		\$ 748,84	748,845 Administration Building Complex			-	-	
=	Total TX		L	(A)	24,780,280 \$			\$ 59,723,338	8			-	-	
TOTALS	TOTALS ALL LOCATIONS		-	es.	51,099,710 \$	32,468,955 \$	33,874,164	\$ 117,442,829				+	-	
ion of the control of	Company Designate Intomedian		-					\$ 47,202,000	0			1	-	-+
Digital Desires and	ricos intendencia							\$ 28,683,450	0			-		_
Scrieduled	Scrieduled Equipment Conformed to one Item prester than \$250 000	m orester than \$25	0000					\$ 5,000,000	C				+	\neg
Blankel Leas	אמתעפוונפת באמוסווופוווים סויב ווא	100000000000000000000000000000000000000	_					\$ 10,000,000	0			+		_
Bianket Or tr	Bianket Oric	meti ego voe	-					\$ 3,000,000	0				1	-
Dializer Carrie	מתוליוויופווו וכפס חומוו ליייילים	-	-	s	\$ 01,039,710 \$	32,468,955 \$	33,874,164	\$ 211,328,279	on'		_		-	_
TOLAT			-			-								

Case 1:10-cv-01653-JPO -JLC Document

Signal International, LLC Equipment Schedule 1/16/2009

Proprietary Information

148 1889 1894 1					Model	SN		Value	Status PO#
	*******						شبندندند		
1980 1981						6560	\$	695,000	Owned
0102					45-275-180	6165	\$	4,000,000	Owned
Manillowoc Ringer Crane 4100W Series 2 41558 \$ 1,230,000 Moned (On m/v *Miss Tiff*) Manillowoc Ringer Crane 4100 41524 \$ 2,000,000 Moned (On m/v *Mis Tiff*) Manillowoc Ringer Crane 4100 41524 \$ 2,000,000 Moned (On m/v *Mr. T) Manillowoc Ringer Crane 45-275-180 5164 \$ 4,000,000 Moned (On m/v *Mr. T) Moned (On m/v *M	0182				M250 Series-2	250 1111	\$	1,500,000	Owned
Manillowo Ringer Crane 4100 41524 5.8 1,280,000 0,0med (On m/w 'Miss Tiff') 1,7100 2	0050	East	Manitowoc	Crawler Crane	4100 W	413001	\$	1,100,000	Owned
1/10 1/10	0068	East	Manitowoc	Ringer Crane	4100w Series 2	41558	\$	1,250,000	Owned (On m/v *Miss Tiff*)
17-100	0221B	East	Manitowoc	Ringer Crane	4100	41524	\$		
Face Face Female Fema	97-100	East	Kenworth	Heavy Hauler & trailers		143706K	\$	1,000,000	Lease to Purchase from GE Capital
East Stark a Tower \$ 200,000 Owned Owned	1309	East	Wash, Iron	Gantry Crane	45-275-180	6164	\$ -	4,000,000	Owned
East Ganity Crane Beam \$ 1,100,000 Owned		East		Elevator Stair & Tower			\$	270,000	Owned
Total Part		East		Stair & Tower			\$	200,000	Owned
Manilowac		East		Gantry Crane Beam			\$	1,100,000	Owned
0090 West Maniltowoc Ringer Crane 4600 Series 5 460078 \$ 2,200,000 Owned → □ <td>TOTAL</td> <td></td> <td>ARD</td> <td></td> <td></td> <td></td> <td>\$</td> <td>17,465,000</td> <td></td>	TOTAL		ARD				\$	17,465,000	
Part				Ringer Crane	4600 Series-5	460078	\$	2,200,000	Owned
Total MS Charge Point Facility Maniform MS MS MS MS MS MS MS M	0017	West	Manitowoc	Crawler Crane	4000 W	401446	\$	620,000	Owned
Total MS Scheduled Equipment Signature Signatur	0178	West	P&H	Platten Bridge Crane		CD-31066-BB	\$	250,000	Owned
1902 Orange Manilowoc Crawler Crane 3900 39610 \$ 150,000 Owned Owned Orange Sebulaham Steel Orange Crane 400 Ton Stiff Leg Sebulaham Steel Orange Manilowoc Orange Manilowoc Orange Musicor Orange Orange Musicor Orange O	TOTAL	WEST Y	ARD				\$	3,070,000	
Total South Manitowoc Crawler Crane A00 Ton Stiff Leg \$800,000 Owned (On m/v 'Big Bessie')	Total N	1S Sched	luled Equipment				\$	20,535,000	
Total Corange Levingston Crane Crane Crane Crane M250 Series-2 250 1110 \$ 1,500,000 Comed (On m/v 'Pelican') Comed Crawler Crane M250 Series-2 250 1110 \$ 1,500,000 Comed	1902	Orange	Manitowoc	Crawler Crane	3900	39610	\$		
Orange Crawler Crane M250 Series-2 250 1110 \$ 1,500,000 Crawler Crane M250 Series-2 250 1110 \$ 1,500,000 Crawler Crane M250 Series-2 250 1110 \$ 1,500,000 Crawler Crane Crawler Crane LR1280 w/200' 136027 \$ 2,700,000 Crawler Crane Crawler Crane LR1280 w/200' 136027 \$ 2,700,000 Crawler Crane Crawler Crane LR1280 w/200' 136027 \$ 2,700,000 Crawler Crane Crawler Crane Crawler Crane LR1280 w/200' 136027 \$ 2,700,000 Crawler Crane Crawler Crane Crawler Crane LR1280 w/200' 136027 \$ 2,700,000 Crawler Crane Crawler Crawler Crawler Crawler Crawler Crane Crawler Crawler Crawler Crawler Crawler Crawler	7003	Orange	Belhleham Sleel	Crane	400 Ton Stiff Leg			\$800,000	Owned (On m/v *Big Bessie*)
Orange Hyster Fork Lift 18 Ton FO19E01973C \$ 150,000 Lease to Purchase (DeLage Landen)	7011				100 Ton Revolving	}	\$	500,000	Owned (On m/v *Pelican*)
Orange Hyster Fork Lift 18 Ton FO19E01973C \$ 150,000 Lease to Purchase (DeLage Landen)	0181	Orange	Manitowoc	Crawler Crane	M250 Series-2	250 1110	\$	1,500,000	Owned
Orange Orange Orange Orange Orange Orange Orange Orange Unitable Orange Oran				Fork Lift	18 Ton	FO19E01973C	\$	150,000	Lease to Purchase (DeLage Landen)
Orange Kenworth Heavy Hauler & trailers 143706K 1,000,000 Lease to Purchase from GE Capital		ļ		Fork Lift	18 Ton	FO19E02071C	\$	150,000	Lease to Purchase (DeLage Landen)
North Very North Heavy Hauter & trailers 143706K 1,000,000 Lease to Purchase from GE Capital		Orange	Liebherr	Crawler Crane	LR1280 w/200'	136027	\$	2,700,000	Leased
Total Orange Y Tot				Heavy Hauler & trailers		143706K	\$	1,000,000	Lease to Purchase from GE Capital
Total North Yard Total Nort	Total (\$	6,950,000	·
4021 South Manitowoc Crawler Crane 4000 W 40242 \$ 200,000 Cwned				Elevator	US-60-1RNU		\$	250,000	Lease to Purchase (Wachovia)
South Groves Cherry Picker RT860 221151 \$ 463,450 Leased from H & E Equipment Lease #83802/T32461	Total I						\$	250,000	
Total North Yard \$ 663,450	4021	South	Manitowoc	Crawler Crane	4000 W	40242	\$	200,000	Owned
North Generator w/ Fuel Tank \$ 285,000		South	Groves	Cherry Picker	RT860	221151	\$	463,450	Leased from H & E Equpment Lease #83802(T32461
North Yard	Total S	<u> </u>	rd				\$	663,450	
Total North Yard \$ 285,000 Total TX Scheduled Equipment \$ 8,148,450		North		Generator w/ Fuel Tank			\$	285,000	
Total TX Scheduled Equipment \$ 8,148,450	Total I	i	rd	1	_L		\$	285,00	
						7-20	\$	8,148,45	
$oxdot{ au}$	Total:							28,683,450.0	g .

Signal Infernational, LLC Five Year Property Loss Experience as of 01/16/09

\$50,000 \$08 \$25,000 \$5.		3° - 3- G	00010		Occurrence	Refained	Paid By
5/28/2004 Power Surge 6/22/2004 Wind Damage (not named) Total No Losses 9/24/2007 Tropical Storm Humberto 9/13/2008 Hurricane Starm 9/13/2008 Windstorm Damage (not named)□to t \$16,387,659 \$1,000 908 25,000 1,006,618 7,435,102 7,435,102 1,006,618 \$1,007,889 \$1,017,889 \$1,017,2007 Tropical Storm Humberto 9/14/2007 Tropical Storm Humberto 100,000 11/8/2007 Crane Overtum 100,000 11/8/2007 Drydock AFDB Flood 100,000 11/8/2008 Windstorm Damage (not named)□to t \$25,000,000 \$1,13/2008 Hurricane Ike™ \$25,000,000 1077/2008 Drydock Damage \$25,140,000 \$1,007,000 \$1,007,000 \$1,007,2008 Drydock Damage \$25,140,000		5	Loss	ALAE	Deductible	By Insured	Carrier
Total 8/29/2005 Hurricane Katrina 8/16,387,659 8/1,017,889 8/1,017,889 8/1,017,889 1,006,618 Total No Losses S0 Total No Losses \$16,387,659 \$23,822,761 \$23,822,761 \$25,000 \$250,000 \$250,000 \$250,000 \$250,000 \$11/6/2007 Crane Overturn \$10,000 Total \$251,000,000 \$11,000,000 \$250,000 \$250,000 \$11,000,000 \$250,000 \$11,000,000 \$	2004-2005	5/28/2004 Power Surge	25,000	908	25,000	25,000	908
8/29/2005 Hurricane Katrina \$16,387,659 \$1,017,889 \$1,017,889 \$1,017,889 \$1,017,889 \$1,017,889 \$1,017,889 \$1,017,889 \$1,017,889 \$1,017,2008 Drydock Damage (not named)□to \$7,435,102 \$150,000 \$1,000,	2027-1007	Total	\$50,000			\$50,000	806\$
Total \$23,822,761 No Losses \$0 Total \$0 9/14/2007 Tropical Storm Humberto \$150,000 11/6/2007 Crane Overturn 264,475 12/17/2007 Drydock AFDB Flood 100,000 75/15/2008 Windstorm Damage (not named)□to i \$65,000 \$1/3/2008 Windstorm Damage (not named)□to i \$65,000 \$1/3/2008 Urricane ike** \$75,000 \$1/3/2008 Drydock Damage \$25,000,000 \$25,140,000 \$25,140,000	2005-2006	8/29/2005 Hurricane Katrina 9/24/2005 Hurricane Rita	\$16,387,659 7,435,102		\$1,017,889 1,006,618	\$1,017,889 1,006,618	\$15,369,770 6,428,484
Total \$0 Total \$0 Total \$0 9/14/2007 Tropical Storm Humberto \$150,000 \$250,000 11/6/2007 Crane Overturn 264,475 50,000 12/17/2007 Drydock AFDB Flood 250,000 250,000 Total \$514,475 250,000 5/15/2008 Windstorm Damage (not named)□to i \$65,000 \$1,000,000 \$1,000,000 9/13/2008 Hurricane Ike** \$75,000 \$1,000,000 107/12008 Drydock Damage \$25,140,000 \$25,140,000	2007		\$23,822,761	·		\$2,024,507	\$21,798,254
Fotal \$0 9/14/2007 Tropical Storm Humberto \$150,000 \$250,000 11/6/2007 Crane Overturn 100,000 264,475 12/17/2007 Drydock AFDB Flood \$514,475 250,000 Fotal Fotal \$514,475 Fotal \$514,475 S51,000 \$1,000,000 9/13/2008 Windstorm Damage (not named)□to 1 \$75,000 \$1,000,000 9/13/2008 Hurricane Ike*** \$75,000 \$10/7/2008 Drydock Damage \$25,140,000 \$25,140,000 \$25,140,000	2006.2007	NO NORMAN	O\$			\$0	\$0
9/14/2007 Tropical Storm Humberto \$150,000 264,475 50,000 50,000 11/6/2007 Crane Overturn 100,000 100,000 250,000 250,000 250,000 250,000 250,000 250,000 8514,475 \$514,475 \$514,475 \$51,000,000 \$1,000,000 \$1,000,000 \$1,000,000 \$1,000,000 \$1,000,000 \$25,000,000 \$25,140,000 \$25,140,000	007-007		0\$			\$0	0\$
### #################################	2007-2008	. ~	\$150,000 264,475 100,000		\$250,000 50,000 250,000	\$150,000 50,000 100,000	\$0 214,475
5/15/2008 Windstorm Damage (not named)□to { \$65,000 \$1,000,000 \$1,000,000 \$1,000,000 \$1,000,000 \$1,000,000 \$1,000,000 \$1,000,000 \$800,000 \$800,000 \$25,140,000		, most in 1007/1	\$514,475			\$300,000	\$214,475
\$25	2008-2009	5/15/2008 Windstorm Damage (not named)□to 1 9/13/2008 Hurricane tke***	\$65,000 \$25,000,000 \$75,000		\$50,000 \$1,000,000 \$800,000	\$65,000 \$1,000,000 \$75,000	\$0 \$0 \$0
		- 1	\$25,140,000			-	\$0 \$
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				÷	

** Claim open, gross value and deductible pending

3/22/2010

Signal International, LLC Five Year Property Loss Experience as of 01/16/09

Daid By	2 2	Carrier	
Dotainod	Netallien	By Insured	
	Occurrence	Deductible	
		ALAE	
	Gross	Loss	
		Cause / Peril	
0.000	Date of	Loss	
100	200	Period	

1/28/2009

Willis

Signal International, LLC Five Year Property Loss Experience as of 01/16/09

	Date of		5507F)		מבנים בינים		
Period	Loss	Cause / Peril	Loss	ALAE	Deductible	20	Carrier
3		5000000				1	
		,					
			•				

1/28/2009

1/28/2009

Retained Occurrence Deductible Gross Loss Date of Policy Period

Cause / Peril

Loss

Paid By Carrier

By Insured

ALAE

Signal International, LLC Five Year Property Loss Experience as of 01/16/09

Willis

Willis

BUSINESS INTERRUPTION Worksheet - Consolidated

Signal International LLC

,		Actual Results for the Fiscal Year Ending 12/31/07	Estimated Results for the Fiscal Year Ending 12/31/08	Estimated Results for the Next Fiscal Year Ending 12/31/09
#	Pre-Tax Operating Profit from the Profit/Loss Statement (unaudited)	\$ 45,682,000	\$ 51,019,000	\$ 23,379,000
#	Payroll, Payroll Taxes, Employee Benefits and Workers' Compensation for:			
	a. Principals, Officers, Managers, Essential Employees and Employees Under Contract (Administration)			
	,	\$ 5,191,000	\$ 4,411,000	\$ 4,411,000
	b. All Other Employees (Production)	\$ 19,643,000	\$ 23,142,000	\$ 13,397,000
#	Fixed Costs and Normal Operating Expenses that Continue to Accrue Even if Business Operations are Interrupted (e.g. utility cost, rent, taxes)		: .	
	·	\$ 8,389,000	\$ 6,015,000	\$ 6,015,000
#	Total Business Interruption Exposure (1+2a+2b+3)	\$ 78,905,000	\$ 84,587,000	\$ 47,202,000
#	To Exclude Business Interruption Coverage on Ordinary Payroll, Subtract Line 2b. Click on option (Exclude) (Include)			
#	Total Business Interruption Exposure Excluding Ordinary Payroll (4 minus 5)	\$ 78,905,000	\$ 84,587,000	\$ 47,202,000
#	To Limit Coverage on Ordinary Payroll (Line 2b) to 30, 60, 90 or 180 Days, enter option			
	here: Click on option below to calculate (30) (60) (90) (180)	\$ -	\$ -	\$ -
#	Total Business Interruption Exposure Including Limited Ordinary Payroll: Total Lines 6 + 7	\$ 78,905,000	\$ 84,587,000	\$ 47,202,000
Cli	ent Signature		Date	Date



Signal International Mississippi & Texas Facilities

PROPERTY RISK ASSESSMENT REPORT SHAI Project No. 01-2008-12-09

Final Version 2.0

Prepared: January 2009



Professional Risk Consulting - Insurance / Brokerage / Industry/ Energy / Utilities / Petrochemical / Chemical/ Refining/ Industries
19423 Lenfwood Lane; Houston, TX 77084; Tel: (281) 579-2004; shellen/enhairisk.com

Signal International LLC SHAI Project No. 01-2008-12-09

Final Version 2.0

Property Risk Assessment January 2009

Notice

Stephen Heller & Associates, Inc. (SHAI) made every reasonable effort to perform the work contained herein, in a manner consistent with high professional standards.

The work was conducted on the basis of information made available to SHAI. Neither SHAI nor any person acting on its behalf makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of this information. All observations, conclusions, and recommendations contained herein are relevant only to the project, and should not be applied to any other facility or operation.

Any third party use of this report or any information or conclusions contained therein shall be at the user's sole risk. Such use shall constitute an agreement by the user to release, defend, and indemnify SHAI from, and against any, and all liability in connection therewith (including any liability for special, indirect, incidental, or consequential damages), regardless of how such liability may arise.

SHAI regards the work that it has done as advisory in nature. The responsibility for the use and implementation of the conclusions and/or recommendations, when applicable, contained herein rests entirely with the client.

Acknowledgements

The following people were instrumental in gathering information, answering questions, and assisted SHAI in order to prepare this report:

Lisa Spears, Signal International Corporate Risk Manager Collin Stevens, Signal International Loss Prevention Manager Stephen Schwartz, Signal International Security Manager Dorian Geraci, Global Special Risks, Houston

Their efforts and hospitality are greatly appreciated.

Property Risk Assessment January 2009

TABLE OF CONTENTS

Executive Summary	5
Risk Summary	6
Summary of Operations, Ownership, Staffing	9
Pascagoula Site Descriptions	13
East Yard	13
West Yard	17
Pascagoula (East / West Yard) Site Risk Characteristics	20
Texas Facility Site Descriptions	23
Orange Yard	23
Dock Yard	25
North Yard	28
South Yard	30
Texas Facilities Site Risk Characteristics	32
Loss Estimate Discussions	35
Loss Estimates	36
Probable Maximum Loss (PML)	36
Propable Maximum Loss (PML)	36
Maximum Foreseeable Loss (MFL)	30
Natural Hazard Loss Estimates	າ ອອ
Recommendations/Observations	Ji
Wind and Storm Surge Analysis (Additional information is provided in the Appendix)	41
Analysis Summary	40
Analysis Description	41
Tropical Storm / Hurricane History & Exposure	47
Texas Facilities	42
Micriscipal Escilities	

Appendices:

- References
- Facilities Building Data
- Wind and Surge Analysis Information (Flood Zone / Water Surge Data)
- Signal International Organizational Chart
- Various Signal Loss Prevention Programs
 - o EHS Management Plan Table of Contents
 - EHS Manual Table of Contents
 - o Fire Response Plan Table of Contents
 - o Incident Plan
 - o JRA Permit to Work System
- Photographs

Final Version 2.0

Property Risk Assessment January 2009

Facilities are located in the Gulf Coast region of the United States and include:

Major Mississippi Facilities:

The Mississippi facilities include The Pascagoula East Yard, which is a rig manufacturing facility, and the Pascagoula West Yard. Both facilities can provide offshore rig repair, upgrade and conversion and are located to allow unrestricted access to the Gulf of Mexico to accommodate large marine projects. These Mississippi facilities have a towable dual carrier dry dock. Adjacent properties to Pascagoula West Yard include an office, training and worker camp facilities. The Pascagoula East facility has employed over 1,500 people. Manpower employed varies due to the seasonal nature of the work with the highest employed levels between summer and early winter months.

Major Texas Facilities:

The Texas facilities include the Orange Yard and Port Arthur North/South/Dock Yards.

The Orange Yard is a heavy marine metal fabrication plant that has similar capacities as described for the Pascagoula East Yard. This yard was formerly owned by Trinity Shipyard and American Bridge. The Port Arthur Dock Yard was formerly operated by Texas Drydock, and it used for major modifications, conversions, repair and drydocking of semi-submersibles, jackup drilling rigs, drillships. The North and South Yards are used for offshore marine ship and rig repair, upgrade and conversion. The Dock Yard includes a normally non-towable drydock.

Final Version 2.0

Property Risk Assessment January 2009

List of Tables

Table 1: East Yard Data	14
TABLE 2: EAST YARD VESSELS	15
TABLE 3: WEST YARD DATA	18
TABLE 4: ORANGE YARD DATA	24
TABLE 5: ORANGE VESSELS	24
TABLE 6: DOCK YARD DATA	26
TABLE 7: NORTH YARD DATA	28
TABLE 8: SOUTH YARD DATA	30
TABLE 9: PML LOSS ESTIMATES	36
TABLE 10: MFL LOSS ESTIMATES	37
TABLE 11: WIND AND WATER SURGE LOSS ESTIMATES	41
<u>List of Figures</u>	
FIGURE 1: MAP OF SIGNAL LOCATIONS	10
FIGURE 2: EAST YARD LAYOUT MAJOR BUILDINGS	
FIGURE 3: WEST YARD LAYOUT MAJOR BUILDINGS	17
FIGURE 4: ORANGE YARD LAYOUT MAJOR BUILDINGS	23
FIGURE 5: DOCKYARD BUILDING DATA	
Figure 6: North Yard Building Data	29
FIGURE 7: SOUTH YARD BUILDING DATA	3:
FIGURE 8: HISTORICAL HURRICANE TRACK STORM SURGE DATA (WWW.MAPS.CSC.NOAA.GOV/HURRICANES/)(NOTE	
(HURRICANE IKE IS NOT INCLUDED IN THIS DATA).	43
FIGURE 9: HISTORICAL HURRICANE TRACK STORM SURGE DATA (WWW MAPS CSC NOAA GOV/HURRICANES/)	

Final Version 2.0

Property Risk Assessment January 2009

Executive Summary

SHAI, as requested by Signal International, carried out a risk review at their principle Mississippi and Texas facilities. The onsite surveys were conducted December 8 & 9, 2008.

The evaluation of the facilities focused on Fire/Allied and Machinery Breakdown Perils, as they relate to property damage and business interruption. This Risk Analysis Report has been prepared to assist underwriters in evaluating the exposures, operations, and loss prevention for the Signal International gulf coast properties. The report is based on information obtained and observations made during the site visit. No tests of fire protection equipment were conducted during this survey.

This risk review provides a systematic, independent assessment, with emphasis on the following:

- Construction, operations and protection features for each facility reviewed;
- Risk exposure potential to operations from fire and equipment breakdown;
- Estimation of loss estimate potentials resulting from risk exposures; and
- Description of exposure and potential estimated loss estimates due to wind and water surge from tropical storm exposure.

The report includes information for the following facilities:

- Pascagoula East Yard and Resident Housing
- Pascagoula West Yard
- Port Arthur Dock Yard
- Orange Yard
- Port Arthur North Yard
- Port Arthur South Yard

Final Version 2.0

Property Risk Assessment January 2009

Risk Summary

Signal International is a diversified marine construction firm engaged in the repair, upgrading and conversion of offshore oil and gas rigs, and the construction and repair of civil and governmental marine transports. Signal operates six shipyards and employs up to 3,000 people.

It is the opinion of the writer that Signal International, at the time of the surveys, has implemented an effective loss prevention program, as described within this report. There were no recommendations developed from this review. Previous insurance recommendations reported in 2003 are provided for historical purposes and are completed.

The activities conducted at these facilities are recognized by the marine and fabrication services industry as proven and well recognized technologies which are typical and consistent with the industry.

Key Risk Summary Characteristics:

- The inherent hazards are typical to the marine repair and fabrication industry and are considered moderate for the use of metal fabrication and platform staging equipment, e.g. cranes, welders, cutters, electrical and dry dock equipment.
- The sites have implemented loss preventive measures (e.g. equipment design, training, maintenance, inspection, safe work practices, etc.) and protective features (e.g. fire protection systems, etc.) in place to address hazards typical to the occupancy.
- The sites reviewed have open layouts, which reduces the likelihood of a large-scale accumulated loss.
- The most probable exposure for property and business interruption would be from machinery breakdown, collapse or fatigue damage related to large crane and dry dock structural equipment, combined with associated damage to other adjacent equipment or common operations.
- The sites, under the current owner's insurance program, have a good loss record and demonstrate strength in risk reduction and control.
- The physical design of the facilities incorporates a combination of redundancies, equipment sparing, alarm and shutdown controls, and environmental control systems, which reduce the potential property damage or business interruption potential.
- Business interruption can be mitigated due to redundancy in operations between the Texas and Mississippi operations.

Property Risk Assessment January 2009

- Facilities are located within 20 miles of the Gulf Coast and have the potential
 exposure to the effects of wind and flooding due to tropical storms and hurricanes.
 Insurance claims have resulted following hurricanes Ike (2008) and Katrina (2005).
 Signal has implemented improvements following each event (lessons learned) at
 their facilities to mitigate future exposures.
- The maximum foreseeable loss (MFL) or worst case scenario for these facilities
 considers a sinking or structural collapse of a dry dock at the Pascagoula East Yard
 or Port Arthur Dock Yard or the accumulated effects of a hurricane to the Pascagoula
 or Orange / Port Arthur properties. Other possible worst case situations would be
 complete loss of the East Yard Administration Building or Resident Housing Facilities
 due to fire.
- Other probable maximum losses (PML) large loss situations could be due other equipment failures related to drydock, cranes, other heavy lifting equipment, welders or plasma cutters.

Notable loss preventions and safety improvements noted during the survey included:

- Established OSHA safety goals in 2008 which includes every Signal employee attending a shippard safety meeting addressing the safety management steps to be employed for that days work. These meetings and safety management techniques are conducted throughout all of Signal's operations as developed by Signal's Environmental, Health & Safety and productions departments and are endorsed by Signal management.
- Signal is acknowledged by the Shipbuilder's Council of America for the annual safety award presented to the operations with the lowest Total Recordable OSHA Incident Rate. Signal has received the Excellence in Safety Award for three consecutive years; and has surpassed the US shippard industry for OSHA total recordable incident rates by a factor of twenty times better, which recognizes Signal to be one of the safest shippards in the marine fabrication industry.
- Improvement to facilities and management programs plans following lessons learned from Hurricane Ike (2008) and Katrina / Rita (2005) include:
 - Improvement to hurricane response plans; i.e. relocation of key equipment; equipment securing strategy; elevation of key machinery and electrical equipment;
 - Structural improvements to help mitigate higher elevations of water accumulation during tropical storms; newly constructed areas or repaired facilities previously damaged during flooding;
 - o Improvements for securing large marine equipment docked at bulk heads during storm events;

Property Risk Assessment January 2009

Summary of Operations, Ownership, Staffing

Signal International, LLC is a leading Gulf of Mexico provider of marine and fabrication services. Signal has four yards in Texas and two in Mississippi and provides services such as:

- New construction of Mobile Offshore Drilling and Production Units (MODUs and MOPUs).
- Upgrading, conversions, overhauls, repairs, and surveys of MODUs and MOPUs.
- On-location work (e.g. mooring system enhancements) done on board.
- Fabrication to military specifications of ship modules for US Navy vessels.
- Dry docking of large and small vessels to facilitate work on lower hulls, pontoons, propulsion/thruster systems, etc.

Signals' offshore segment customers consist primarily of drilling contractors that drill offshore exploratory and development wells for oil and gas companies throughout the world, particularly in the Gulf of Mexico, the North Sea, Eastern Canada, West Africa, South America, other offshore areas of the world, and other parties that intend to lease newly constructed rigs to drilling contractors. Signal is expanding their core business in the area of modular construction and fabrication for the U.S. Navy.

Semisubmersible and jackup rigs, large and small, can be dry docked at Signal International's yards both in Mississippi and Texas. Work such as pontoon or spud repair, steel replacement, thruster/propulsion repair, addition of sponsons and blisters, is routinely carried out on the dry docks. Signal provides the docking plan, the cribbing and the engineers and dockmasters to ensure safe, secure and ready access to the rig's belowwaterline extremities. The dock yard also facilitates the fabrication of large marine modules that can be skidded or lifted off for transport to another site for mating with the host vessel.

Overall facilities Capabilities:

- Covered and open fabrication capability
- Dry docks
- Wide deepwater channel access to GOM
- Water frontage
- High capacity mobile cranes
- · Inside blasting, burning, welding and painting equipment
- Machines shops
- Pipe fabrication shops

Final Version 2.0

Property Risk Assessment January 2009

- Portable electrical equipment modified to allow the equipment to be elevated prior to a tropical storm;
- Electrical substation damaged during previous storms are built on elevated platforms; and
- Orange Facility: Major electrical conduit runs relocated from previous lower build elevation to 12 feet or higher throughout the facility. This modification is based on a lesson learned from previous highest flooded elevations of 8-10 feet.

Overall, the Signal International facilities reviewed are rated as an "Above Average" risk as it relates to insurance property and boiler machinery coverage.

The opinions expressed regarding the quality of risk are based on similar industries located throughout the gulf coast United States.

The ratings are further defined as:

Good = Best practices consistent with industry leader

Above Average = Acceptable standards including some industry best practices

Average = Acceptable standards, no major recommendations

Below Average = Some practices are less than acceptable, with major recommendations


Poor = Significant deficiencies exist

Property Risk Assessment January 2009

- Module platens
- Testing and calibration equipment
- Fixed and portable office space
- Warehouses
- Joiner fabrication and outfitting facilities
- Jigs and fixture for work related to such activities as jackup leg fabrication

Further details of Signal's capabilities can be found at their website: www.signalint.com.

Figure 1: Map of Signal Locations



Case 1:10-cv-01653-JPO -JLC Document 167-12 Filed 08/10/12 Page 46 of 65

Signal International LLC SHAI Project No. 01-2008-12-09

Final Version 2.0

Final Version 2.0

Property Risk Assessment January 2009

Pascagoula Site Descriptions


East Yard

The Pascagoula East Yard operations are located in Pascagoula, Mississippi. The facility is situated on the Gulf of Mexico on the Bayou Casotte Harbor. The harbor can accommodate a wide variety of cargo and is supported by a strong transportation infrastructure.

The site is within a couple miles of Interstate 10 and the State Highway system. Pascagoula rail service begins at the terminal of Bayou Casotte Harbor. Rail service connections are the CSXT and Mississippi Export Railroad, which connects to Illinois Central Railroad.

The East yard has dockside and unobstructed access to the Gulf of Mexico, on Bayou Cassotte, located eight miles from the Sea Buoy via a 300' wide, and 38' depth channel.

Figure 2: East Yard Layout Major Buildings



Final Version 2.0

Property Risk Assessment January 2009

Primary facility features are listed in the table below.

Table 1: East Yard Data

East Yard	
601 Bayou Casotte Parkway	
Pascagoula, MS 39581	
Total Acreage:	94 acres
Total Building Area:	273, 054 sq. ft.
Water Frontage:	2,000 ft.
Water Depth:	35 fl MLLW
Distance to Open Sea:	13.5 nm
Fabrication Area:	
Covered:	100,000 sq. ft.
Outside:	362,000 sq. ft.
Quayside Facilities	002,000 Sq. 1L
Outfitting/Repair Docks	•
Type:	Concrete bulkhead
Length:	2,000 ft.
Water Depth:	2,000 k, 35 ft.
Principle Site Equipment	งวาเ.
	•
Cranes/Cherry Pickers/Forklifts	66-611 - 64-614-00 4000
3 ea; 150 ton	Mobile Manitowac 4000
2 ea; 300 ton	Mobile Manitowoc M250
2 ea; 125 ton	Washington Gantry Crane
2 ea; 300 ton	Floating Manitowoo 4100 Ringer
8 ea; 15 ton	Cherry Pickers
6 ea; 2.5-12 ton	Forklifts
14 ca; 15 - 40 ton	Overhead Bridge Cranes
1 ea; 40 ton	Bridge-Kraco
Major Shop (Fabrication) Equipment	
1 ea	Wheel-A-Brator, BCP Auto Blast Machine
t ea	Wheel-A-Brator, BCP Auto Paint Machine
2 ea	Piranha Iron Worker
i ea	N/C Plasma Burning Table
1 ea	N/C Flame Burner
1 ea	One-sided Butt Welder
1 ea	Angle Stiffner Fitter
1 ea	Stiffner Welder
310 ft.	Panel Line
Machine Shop Equipment	
1 ea	Schiess Boring Mill-11' Vertical Travel, 55' Horizontal Travel
1 ea	Gray Boring Mill- T' Vertical, 25' Horizontal
1 ea·	Cincinnati Floor Mill- 6' Vertical, 4' Horizontal
3 ea	Small Mills
1 ea	17" Tum-nado Southbed Lathe
1 ea	Monarch Lathe, 10' Bed, 96" Center
1 ea	Kingston 21°-27° Gap Bed Lathe
1 ea	Drill Presses
Dual Carrier Drydock	Towable dudock in the Gulf of Maxima with because the engaging
	Towable drydock in the Gulf of Mexico with heavy lift capacity

Final Version 2.0

Property Risk Assessment January 2009

Pascagoula (East / West Yard) Site Risk Characteristics

ASSESSMENTS PASCAGOULA	Comments - For Both West/East Yards ; Except Where Indicated Otherwise			
SITE LAYOUT / FIRE DIVISION	Spacing between building and to other properties is well laid out separating different occupancies, e.g. equipment, fabrication and repair, offices, warehouses and residential houses (Resident Housing East Yard Only). Each individual area is considered a separate fire division.			
	Typical runoff drainage is to the water way adjacent to the property. This operation does not require extensive piping or liquid handling systems.			
	East Yard: Congestion is considered light in the repair and fabrication areas and moderate to heavy in the Resident Housing area. An incident should be contained to the area of development, i.e. specific equipment area, office building or Resident Housing. The East Yard has a varying uphill elevation change from the waterway to the facilities.			
	West Yard: Congestion is considered light throughout. The West Yard has flat terrain in the fabrication and main yard and uphill elevation changes out to the training building.			
CONSTRUCTION	A full listing of buildings construction and occupancy is provided in the Appendix. The majority of the building square footage is primarily non combustible construction with the exception of the office Resident Housing buildings (East Yard) which are primarily combustible construction (see Appendix).			
	Facilities are built in accordance with insurance/ASME/Building codes for windstorm/temperature extremes/flooding/hurricane potential anticipated for geographic area.			
	Computer controlled cutting machines are used in the Fabrication Shop. Equipment is controlled by the crafts person operating the machine with typical safety shutoff systems. The equipment does not operate unmanned. Emergency shut off "kill switches" are specific to the equipment being used such as welders, cutting machines, etc.			
	There is no significant use of liquid storage tankage at the facilities.			
•	Vehicular protection is provided for above ground systems. Primary roads and parking areas are paved.			
LOADING/ UNLOADING	Receipt of raw materials and distribution of products can be performed by rail, truck, or marine vessel. Bulk receipts would be plate steel and equipment and parts associated with rig work.			
	Fabricated onshore components are transferred by crane for attachment to the rigs. Large lifts are performed by a gantry cranes, e.g. land, floating and mobile.			
OTHER STORAGE	The East Yard has three separate warehouses provided on site. Two of the three are leased to clients. One warehouse contains consumables and equipment, mostly metal parts. During the survey, minimal storage was noted in the leased spaces. Each warehouse is considered a single fire area. The West Yard has smaller storage building areas with minimal content.			
	The East Yard has a large area south of the Resident Housingfacilities used for outside storage of metal material and idle equipment.			
OPERATIONS/ PROCESS	This operation primarily handles the fabrication, retrofit and repair of heavy metal fixtures and equipment associated with offshore drilling rigs and associated marine structures. With the exception of the warehouses, Resident Housing and offices, the majority of principle building are considered metal working occupancies in which metal is the basic material involved in the manufacturing/fabrication of attachments or portions of drilling rigs or similar marine style objects. This includes occupancies typical to machine, metal working, cutting & welding, assembly metal and metal repair shops. The East Yard Resident Housing is a residential area consisting of connected mobile homes.			
	The primary exposures from the operations area which could result in insurance claim would relate to major equipment breakdown, collapse of crane, dropping of large heavy object or collision at the dock. The primary exposure to fire would be in the Resident Housing area due to a fire.			

Final Version 2.0

Property Risk Assessment January 2009

The following vessels in the table below are located at the site.

Table 2: East Yard Vessels

Vessel	Туре	Size	Material	Description
M/V Maggle D	Tug	50x20.5	Steel	Towboat/Single Skin/Self Propelled
Miss Tiff	Crane Barge	150x60x10	Steel	Deck Barge/Single Skin
MS61	Deck Barge	60x26x5	Steel	Barge/Single Skin
MS64	Deck Barge	60x26x6	Steel	Barge/Single Skin
20' Yamaha 115	Custom	20'	Aluminum	Tender/Single Skin/Self Propelled
21' Yamaha 115	Custom .	21'	Aluminum	Tender/Single Skin/Self Propelled
20' Suzuki 90 HP	Custom	20'	Aluminum	Tender/Single Skin/Self Propelled
Dual Carrier	Submersible DD	368x203x25	Steel	Barge/Single Skin (Dry)
Mr. T	DeckCargo Barge w/ringer crane	140'x54'x9'10"	Steel	Deck Barge/Single Skin
Deck Barge	Deck Barge	50x20	Steel	Deck Barge/Single Skin
Deck Barge	Deck Barge	50x20	Steel	Deck Barge/Single Skin
Deck Barge	Deck Barge	50x20	Steel	Dack Barge/Single Skin
Deck Barge	Deck Barge	50x20	Steel	Deck Barge/Single Skin

Other Pascagoula East Yard features include:

- Design provides for extensive use of automated construction equipment, floating and dockside cranes, panel lines, launch-ways and reinforced bulkhead dock space.
- The maximum lift at 25 meters out from quayside is 200 tons using a single crane.
 However, cranes are used in various combinations to achieve lifts exceeding single crane capacities.
- Electricity (480/3 phase/60 Hz/800 amps), fresh water, salt water, and compressed air, at 110 psi, are available dockside.
- Mobile cranes are used to erect panels into subassemblies; mobile, fixed and bargemounted cranes are used to erect subassemblies; and mobile transporters are used to move subassemblies (any size module up to 525 Tons). The site has two mobile transporters.
- The covered facility offers full machine shop services.
- Pipe pre-fabrication is carried out in a covered shop and is serviced by a 15 ton overhead crane. The shop contains eight (8) welding stations with Sub Arc, Mig, Tig and Flux Core welding capabilities. Pipe bending machine capabilities up to 4". Over 4" can be subcontracted.
- The Electrical Shop facility is utilized for electrical maintenance of all tools, cords, welding machines and other equipment throughout the yard. Temporary lighting, telephone lines, distribution racks and shore power feeder installations for customers are also coordinated from this department where materials required for these installations are maintained.
- · There is a new constructed blasting and painting building (which is used for shop

Final Version 2.0

Property Risk Assessment January 2009

blasting and primer coat). There is also a separate area where protective coatings can be applied in the outside storage and sandblast area.

- The site has three 20,000 sq. ft. warehouses, which provide covered, secure storage for yard consumables, weather sensitive items, and owner-furnished equipment. Two of the warehouses are leased.
- An office building area houses executive, administrative, project and engineering personnel provided at the East Yard. This area is the corporate office location for Signal International. Other office space is located in the production shops, combined with auxiliary trailers, accommodate the production staff.
- Owner and regulatory offices are accommodated by portable on-site trailers. Other trailers are provided by clients and vendors for their use.
- There is a Resident Housing facility used to house contract workers. This area is fenced and separated from the main operations and includes a parking lot. Facilities include 21 bunkhouses and facilities for kitchen, laundry, lounge, shower, officestorage and a guard house.
- The East Yard facility has a dual carrier dry dock which is fully self-contained and transportable. It can service both East and West yards. Orientation of the drydock can be changed to use floating and dockside cranes.

The dimensions of the Dual Carrier dry dock are:

o Clear deck 368' x 203'
o Capacity 30,000 DWT
o Sill height 25'
o Maximum draft 20'

• The panel shop is fully equipped and is served by overhead magnetic cranes. It can process approximately 48,000 tons of steel per year and can handle panels up to 50'x80', with a maximum assembly weight of 80 tons. Panel units are pre-fabricated on a raised assembly line complete with rollers, hydraulic plate leveling, stiffener clamping machines and eight (8) stiffener arc welders. Also located in this shop is the N/C cutting machine equipped with two (2) heads and plasma marking. The main panel shop has 55' x 25' doors and is equipped with 2 x 40 ton overhead cranes with a 25' hook height. The adjacent processing area is served by a 15 ton overhead crane.


Property Risk Assessment January 2009

West Yard

The Pascagoula West Yard facility is situated on the Gulf of Mexico along the Pascagoula River Harbor. The harbor can accommodate a wide variety of cargo and is supported by a strong transportation infrastructure.

The site is within a couple miles of Interstate 10 and the State Highway system. Adjacent properties to the West Yard include an office (rented and insured by tenant) and training buildings at Jerry St. PE Highway.

Figure 3: West Yard Layout Major Buildings



The Pascagoula West facility is located on the Pascagoula River with a 350' wide, direct access channel (with a water depth of 38') to the Gulf of Mexico. The facility has a concrete cap pile reinforced dock at the north end of the Pascagoula River turning basin.

Final Version 2.0

Property Risk Assessment January 2009

Primary facility features are listed in the table below.

Table 3: West Yard Data

West Yard	
3500 Port Authority Road	
Pascagoula, MS 39567	
Total Acreage:	13 acres
Total Building Area:	45, 718 sq. ft.
Water Frontage:	1,100 ft.
Water Depth:	38 ft. MLLW
Distance to Open Sea:	16. 2 nm
Fabrication Area:	
Covered:	47,550 sq. ft.
Outside:	39,000 sq. ft.
Quayside Facilities	•
Outfitting/Repair Docks	
Туре:	Concrete bulkhead
Length:	1,100 ft.
Water Depth:	38 ft.
Principle Site Equipment	<u>.</u>
	Fork Lift Equipment (4)
	Cherry Pickers (5)
	Portable Personnel Elevators (4)
	Floating Cranes (2) 150 t
	Shop Gantry Cranes: Fab Shop 2 – 20 ton Pipe Shop 1- 15 ton Platen 1 – 20 ton/1 – 10 ton
•	4600 Ringer Crane Misc. Barges and Tug (shared with East Yard)

Other Pascagoula East Yard features include:

- Facilities consist of the main berthing dock at the north end of the Port, where the
 main fabrication and pipe shops are located together with module fabrication platens,
 and the blasting and paint yard.
- A covered structural shop building is serviced by two (2) 10-ton overhead gantry cranes. It is equipped with a Template Burning Machine and a chop saw.
- Adjacent to the Structural Shop is a pipe shop. This covered shop is used for pipe pre-fabrication and is serviced by a 5-ton overhead Gantry crane and a 2-ton Jib crane. It is equipped with an NC Burning Machine and an Ironworker.
- There are three concrete fabrication platens used as an assembly area. Platens are open and serviced by all yard equipment from forklifts to 200-ton crawler cranes. Fabrication platens are utilized for assembly areas where practical.

Final Version 2.0

- Assembly and erection can be carried out on the dock directly in front of the rig being worked.
- The electrical maintenance shop is utilized for electrical maintenance of all tools, cords, welding machines and other equipment throughout the yard.
- Projects can be serviced by 150 and 200-ton crawler cranes as well as a 300-ton barge-mounted ringer and a 600-ton land-based ringer Manitowoc crane.
- Electricity (480/3 phase/60 Hz/800 amps), fresh water, salt water, and compressed air, at 110 psi, are available dockside.
- There is a Production office which can accommodate project management and support service offices. Space is available on site for portable office space which accommodates controls, construction superintendents, QA/QC, various customer and customer-subcontract personnel.
- An approximate 20,000 square foot Administration office building is located adjacent to the yard on Jerry St PE Highway. This office is leased and insured by a different company.
- An approximate 12,000 square feet training facility, which also can be used for administrative and other production and engineering offices, is located adjacent to the site on Jerry St PE Highway next to the vacant office.

ASSESSMENTS PASCAGOULA	Comments - For Both West/East Yards ; Except Where Indicated Otherwise
FIXED ELECTRICAL SYSTEMS	Main power is supplied by a local power authority and is considered reliable. Loss of power results in shut-down of the site. Back- up power can be provided to operate portions of the site using portable generation.
	Several small to moderate sized transformers are located on site and owned by the owner. These are reported to be PCB free and are readily available.
UTILMES	Other typical utilities include compressed air provided by small portable equipment and domestic water provided from the public system. Natural gas is used and piped from a local provider.
	Liquid carbon dioxide and oxygen (provided by third party) are stored in tanks in a segregated outside area and used for welding and cutting processes.
MAINTENANCE, REPAIRS & INSPECTION	The maintenance department is comprised of multiple highly qualified crafts: electrical, welder tool worker, and instrumentation. The department at the site handles the majority of day to day maintenance activities, with the majority of the duties related to metal fabrication. Larger projects are completed by qualified contractors.
	Inspection, testing, and maintenance frequencies are established using manufacturers' recommendations and industry guidelines.
	Non-destructive examination (NDE) techniques are utilized as necessary for structural and piping integrity inspections.
	Overall, the programs are established and use written records maintained for equipment and procedures. The maintenance system is run by a ticket system. The majority of the historical records at these facilities were destroyed during hurricanes Katrina/Rita. The facility is in the process of converting over to a computerized records system. No specific date for completion of record system was indicated.
	The site has practices and procedures in place to maintain fire protection systems for systems and equipment. The program utilizes training, procedures, inspections and tests, deficiency corrections, and quality assurance. The maintenance program uses a combination of preventive and predictive maintenance techniques.
CONTRACTORS	The site does not use resident contractors. Living facilities (Resident Housing) are provided at the East Plant for general
	laborers. Specialized contractors are used for large, special jobs depending on the current work projects. Onsite training and supervision are provided for specific tasks for contractors.
OPERATION	Operational procedures are used for major equipment operations. Best Practice between the Mississippi and Texas locations are used as guided per corporate directives. Operating procedures are written and are available for typical operations.
	Formal training for new and existing employees, competency testing and certification; refresher training; safety and technical training are provided.
	Facility personnel involved in hazardous waste management, such as storage of off spec product and response to emergencies, complete a program of classroom instruction or on the job training that teach them to perform their duties.
WORK PERMIT	A work permits system is in place for welding, work order, lockout/tagout, confined space, etc. On major jobs, blanket permits are typically given. Areas typically considered a welding occupancy do not require permitting.
HOUSEKEEPING	Critical areas were clear and non-congested with idle material or equipment.
EMERGENCY RESPONSE	The local fire department and local police are the emergency response for the facilities. A written emergency procedure coordinated with local fire department is in place under the existing plan. The site has an excellent emergency preparedness program and procedures for hurricanes.
FIRE BRIGADE RESPONSE	The site provides typical hazardous material response coordination. The site is considered an incipient emergency response. Fire response for the facility is considered reliable. Access to the facility is considered good.

Case 1:10-cv-01653-JPO -JLC Document 167-12 Filed 08/10/12 Page 56 of 65

Signal International LLC SHAI Project No. 01-2008-12-09

Final Version 2.0

ASSESSMENTS PASCAGOULA	Comments - For Both West/East Yards ; Except Where Indicated Otherwise
	The fire department conducts fire inspections of the East Yard Resident Housing facilities and West Yard Training Building and has historically provided recommendations, which Signal has compiled with.
MANUAL FIRE EXTINGUISHING	Hand and wheeled fire extinguishers are located throughout.
	Fire water is provided by the public water system. At the East Yard, an onsite distribution system consisting of a combination of 8 inch and 6 inch pipes is provided. In addition, the East Yard has several hydrants located throughout the facility. There is a hydrant available at the Resident Housing facilities entrance.
•	The West Yard has fire water available from the adjacent road hydrants.
FIRE PROTECTION SPRINKLER SYSTEMS / DETECTION	Sprinkler systems are provided for main office building areas at the East Yard and Training Building at the West Yard. These systems are hydraulically designed. There is a sprinkler system located in the common areas of the Resident Housing facilities, i.e. laundry room, recreational room and cafeteria. There are no other sprinkler systems at the East or West Yards.
`	The Resident Housing facilities are provided with a smoke detection system throughout, which alarms to a constantly attended location. In addition, fire hose stations are located throughout this area.
EXPOSURES	The East Yard facility is surrounded in three directions by land and to the east by the Bayou Casotte Channel water way. The dockside is approximately 2000 feet long. Immediately across the channel is a Chevron Refinery approximately 1,800 feet away. Mississippi First Chemical is located approximately one mile away across the channel to the north. Exposures from other directions are open land for several hundred yards.
	The West Yard The facility is surrounded in three directions by land and to the east by the Pascagoula River water way. The dockside is approximately 1100 feel long. Immediately across the channel are several non-hazardous facilities. Exposures from the south are Port Authority non-hazardous bulk storage warehouses. To the north is open land for several hundred yards.
	Both Yards are exposed to potential water surge from adjacent water ways and flooding from severe tropical storms. This issue is further discussed in the storm analysis report section.
INTRUSION ARSON TERRORISM	The portions of the property accessible to the public are fenced with access by a 24 hour manned gate. The facilities are accessible from an immediate public road. Vandalism or malicious mischief has not been a problem in past years. Good exterior and perimeter lighting is provided.
	The sites are occupied at all times by workers or by a guard who makes rounds for the East Yard and a guard at the main West Yard facilities (West Yard is currently idle). The West Yard area training building is located outside the fenced West Yard operation on the west side of the property, and the training building is locked and unmanned during non-operating hours. This building is visible from the West Yard guard building.

Property Risk Assessment January 2009

Texas Facility Site Descriptions

Orange Yard

The Orange Yard is a 77 acre facility located in Orange, TX. The yard is used to build mobile offshore drilling and production units as well as components for other rigs. The site is situated near the Gulf of Mexico up river on the Sabine River. The harbor can accommodate a wide variety of cargo and is supported by a strong transportation infrastructure.

The site is near Interstate 10 and the State Highway system. Terminal service is available to the site.


Under former ownership by American Bridge, Inc. (USS subsidiary), the site employed up to 1,800 people who produced multiple marine and offshore products, pressure vessels, bridge girders and other heavy industry products. Government war ships were constructed here during the World War period. The heavy metal fabrication site was acquired in December 1992, by a Trinity Industries subsidiary, which fabricated large diameter pressure vessels there until May 1996. In July 1996, Trinity Marine Products, another Trinity Industries subsidiary began manufacturing barges and barge parts at the site. In May 1998, Trinity's shipyard in Orange, TX was purchased by TDI-Halter L.P, a subsidiary of Halter Marine Group, Inc., prior to Friede Goldman Offshore (FGO) involvement.

This facility was in full operation at the time of the survey. Portions of the facility were undergoing repair from Hurricane Ike (2008).

Figure 4: Orange Yard Layout Major Buildings

Main Fabrication Shors Maintenance Building

Storage Building.



Stomae Building

Buckley Office and Shop

Page 23 of 48

Final Version 2.0

Property Risk Assessment January 2009

Primary facility features are listed in the table below:

Table 4: Orange Yard Data

Orange Yard	
94 W. Front St.	•
Orange, TX 77630	
Total Acreage:	82 acres
Total Building Area:	569, 458 sq. ft.
Water Frontage:	5,700 ft.
Water Depth:	25 ft. MLLW
Distance to Open Sea:	34.3 nm
Fabrication Area:	
Covered:	450,000·sq. ft.
Outside:	20 acres
Quayside Facilities	
Outfitting/Repair Docks	
Type:	Steel Bhd
Length:	623 fL
Water Depth:	22 ft.
Principle Site Equipment .	
Cranes/Cherry Pickers/Forklifts	
1 ea; 150 ton	Crawler Crane
1 ea; 100 ton	Crawler Crane
1 ea; 400 ton	Stiff Leg Denick Barge
1 ea; 100 ton	Revolving Leg Derrick Barge
1 ea; 40 ton	Break Press
Multiple; 35-450 ton	Shop Gantry Cranes
Multiple; 1-15 ton	Assorted Forklifts
Multiple	Assorted Iron Worker Stations (boring presses, band saws, plate shear)
1 ea	Wheel-a-Brator Automated Blast & Prime Machine
1 ea	Panel Line Fabrication consisting of: Series-arc welding machine with: 45-foot magnet bed, 4-head stiffener fitter/positioner, 6-head stiffener welder N/C Plasma Cutters
3 ea	

The following vessels are located at the site:

Table 5: Orange Vessels

Vessel	Description	Dimension	Const.	Description
Quida	Tug	46x24x9	Steel	Towboat/Single Skin/Self Propelled
Pelican	Derrick Barge	198x70x11,5	Steel	Deck Barge/Single Skin
Big Bessie	Derrick Barge	191x83x12	Steel	Deck Barge/Single Skin
Dan B	Tug	25x14x5	Steel	Towboat/Single Skin/Self Propelled
	Deck Barge	34'x120'x7'	Steel	GRT Required
	Boat, "V" Weldbilt	18x56"	Aluminum	Tender/Single Skin/Self Propelled
Monark Boat	Runabout	19x7x3.5	Aluminum	Tender/Single Skin/Self Propelled
Drydock, AFDB-5	Pontoon/Wingwalls	240x101x23.6	Steel	Drydock/Single Skin
DB TDD4	Deck	120x40x8	Steel	Barge/Single
TDD1 TDD3	Work Barge	30x60x5	Steel	Barge/Single Skin
Miss Kathy	Work Barge Deck Barge	24x13x4 36x110x7	Steel Steel	Barge/Single Skin Barge/Single Skin

Case 1:10-cv-01653-JPO -JLC Document 167-12 Filed 08/10/12 Page 59 of 65

Signal International LLC SHAI Project No. 01-2008-12-09

Final Version 2.0

Property Risk Assessment January 2009

Other Orange Yard features include:

- The facility has extensive repair and fabrication facilities with a complete panel line, similar to the Pascagoula East Yard. Panel units are pre-fabricated on a raised assembly line complete with rollers, hydraulic plate leveling, stiffener clamping machines and a stiffener arc welder. In addition, this shop includes an N/C cutting machine and plasma marking.
- The panel shop adjacent to the repair and fabrication areas are fully equipped with overhead cranes.
- Machine shop capabilities.
- Pipe pre-fabrication is carried out in a covered shop and is serviced by an overhead crane. The shop contains welding stations with various welding capabilities.
- The Electrical Shop is utilized for electrical maintenance of tools, cords, welding machines and other equipment throughout the yard. Temporary lighting, telephone lines, distribution racks and shore power feeder installations for customers are also coordinated from this department where materials required for these installations are maintained. The site has a fully equipped paint shop.
- Five warehouses provide covered, secure storage for yard consumables, weather sensitive items, and owner-furnished equipment.
- The main office building area houses executive, administrative, project and engineering personnel. Other office space is located throughout the production shops, including auxiliary trailers and small office buildings to accommodate the production staff.

Dock Yard

The Dock Yard operations consist of the former Friede Goldman Offshore (FGO) facilities located in Port Arthur, Texas. This facility is located on the Neches Waterway. The site is situated within 15 miles of the Gulf of Mexico and has waterway access.

This site is intended to be used to build mobile offshore drilling and production units as well as components for other rigs. This yard is to receive fabricated parts from the Orange Yard which are then installed on the dry docked marine equipment.

At the time of the survey the facility had minimal activity due to workload scheduling. Minimal damage occurred at the site as a result of Hurricane Ike (2008).

The Dock Yard was established by Bethlehem Steel in 1985, and acquired by Texas Drydock, Inc., in 1995. Dock Yard was later owned by HAM Offshore Services and then FGO. This yard has a floating dry dock and is owned by the City of Port Arthur (one of the eight sections is owned by FGO). The facility was designed to specialize in major modifications, conversions, repair and dry docking of semi-submersibles, jackup drilling rigs, drillships, FPSO and FPS.

The facility has a 64,000 ton dry dock that operates in rig mode, with 363 feet between wing walls and is 414 feet long. This versatility affords the ability to drydock nearly every

Final Version 2.0

Property Risk Assessment January 2009

type of drilling rig. It is located on the Sabine Neches Waterway near Port Arthur and Pleasure Island.

Primary facility features are listed in the table below.

Table 6: Dock Yard Data

Dock Yard	
2500 Martin Luther King, Jr. Drive	
Port Arthur, TX 77640	
Total Acreage:	100 acres
Total Building Area:	222,554 square feet
Water Frontage:	4,961 ft.
Water Depth:	55 ft. MLLW
Distance to Open Sea:	14.8 nm
Fabrication Area:	
Covered:	
Outside:	
Quayside Facilities	
Outritting/Repair Docks	· ·
Type:	Berthing Pier
Length:	111.5 ft.
Water Depth:	25 ft.
Principle Site Equipment:	Multi-Wheel Transport
	Forklift Trucks
	Cherry Pickers
	Portable Personnel Elevators
	Floating Cranes (2) 1-400 t stiff leg. (1) 100 t revolving


The following vessels listed in the table below are associated with the Dock Yard:

Other Dock Yard features include:

- Two warehouses provide covered, secure storage for yard consumables, weather sensitive items, and owner-furnished equipment. Currently these are mostly empty.
- The site contains several small office and trailer buildings and offices for administrative, engineering, safety, environmental, production, contractors, and customers use.

Final Version 2.0

Figure 5: Dock Yard Building Data



Final Version 2.0

Property Risk Assessment January 2009

North Yard

The North operations consist of the former Friede Goldman Offshore (FGO) facilities located in Port Arthur, Texas. This facility is located on the Port Arthur Turning Basin and has waterway access. This site is intended to be used to repair and build mobile offshore drilling and production units as well as components for other rigs. The site is situated within 15 miles of the Gulf of Mexico.

North Yard was owned by HAM Offshore Services before FGO. This yard is to receive fabricated parts from the Orange Yard which are then installed on the docked marine equipment.

At the time of the survey this yard was idle and under repair from damage occurred during Hurricane Ike (2008).

Primary facility features are listed in the table below.

Table 7: North Yard Data

North Yard	
2350 S. Gulfway Dr.	
Port Arthur, TX 77640	
Total Acreage:	17 acres
Total Building Area:	14212 sq. ft.
Water Frontage:	1,590 ft.
Water Depth:	25 ft. MLLW
Distance to Open Sea:	14.8 nm
Fabrication Area:	33,000 sq. ft.
Quayside Facilities	·
Outfitting/Repair Docks	-
Type:	Steel Bhd
Length:	879 ft.,
Water Depth:	25 ft.
Principle Site Equipment	Multi-Wheel Transport
	Forklift Trucks
	Cherry Pickers
	Portable Personnel Elevators
	Floating Cranes (2) 1-400t stiff leg, (1) 100t revolving

The following vessels listed in the table below are associated with the North Yard.

Other North Yard features include:


 Two warehouses provide covered, secure storage for yard consumables, weather sensitive items, and owner-furnished equipment.

Page 28 of 48

Final Version 2.0

- The site contains several small office and trailer buildings, offices for guards, administrative, engineering, safety, environmental, production, contractors, and customers use. These buildings are currently mostly empty.
- The site is fenced with a locked gate. The elevation of the structures is approximately 6-8 feet above the water level.
- · This facility does not have a dry dock.

Figure 6: North Yard Building Data



Final Version 2.0

Property Risk Assessment January 2009

South Yard

The South Yard (TDI Sabine Pass) operations consist of the former Friede Goldman Offshore (FGO) facilities located in Sabine Pass, Texas. This facility is located on the Sabine Pass Channel. This site is intended to be used to repair build mobile offshore drilling and production units as well as components for other rigs. The site is situated within 5 miles of the Gulf of Mexico.

At the time of the survey, this facility was idle and under repair from damage incurred from Hurricane Ike (2008).

The South Yard later was previously owned by TDI-Halter Marine and then FGO. This yard receives fabricated parts from the Orange Yard, which are then installed on the docked marine equipment.

Primary facility features are listed in the table below.

Table 8: South Yard Data

South Yard	
6830 S. First Ave.	·
Sabine Pass, TX 77655	
Total Acreage:	21 acres
Total Building Area:	36,787 sq. ft.
Water Frontage:	1,400 ft.
, Water Depth:	20 ft. MLLW
Distance to Open Sea:	6.1 nm
Fabrication Area:	·
Covered:	45,000 sq. ft.
Outside:	300,000 sq. ft.
Quayside Facilities	
Outfitting/Repair Docks	•
Type:	Steel Bhd
Length:	778 ft.
Water Depth:	22 ft.
Principle Site Equipment:	Multi-Wheel Transport
	Forklift Trucks
	Cherry Pickers
	Portable Personnel Elevators
	Floating Cranes (2) 1-400 stiff leg, (1) 100t revolving

Other South Yard features include:

- Warehouse facilities provide covered, secure storage for yard consumables, weather sensitive items, and owner-furnished equipment. Currently, these facilities are mostly empty or under repair.
- The site contains several small office and trailer buildings and offices for guards administrative, engineering, safety, environmental, production, contractors, and customers use. These buildings are currently mostly empty or under repair.
- The facility does not have a dry dock.

Final Version 2.0

Figure 7: South Yard Building Data

